

## WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	L-73/Cameron Hills	Operator:	Strategic Oil and Gas Ltd.
Location of Inspection:	Cameron Hills Production Field	Access method:	Helicopter – Great Slave Helicopters
Site Contractor:	None	Status:	Compliant Suspended – Production Well
Approval Info	OA-2018-003	WID:	2033
Date of Inspection	12/SEP/2019	H2S Site:	Yes

### Summary of Inspection

<b>Activity on site</b>	Gas migration testing and annual well inspections conducted by GChem (Contractor)		
<b>Conditions</b>	<b>Satisfactory (Y/N)</b>	<b>Comments</b>	
Site Access	Y		
Well Head Access	Y		
Signage	Y		
General Housekeeping	N	Rusted metal debris scattered around site is a safety hazard. (Photo # 2) Debris should be removed from site	
SCV Open and dead	Y	0 Bubbles in 10 min at SCV.	

#### Additional Site Hazards:

Potential of H2S Gas exposure, personal monitors worn by inspectors.  
Signs of wildlife (tracks and scat)

#### Comments and Summary:

OROGO Inspection Team: Brian Heppelle (Chief Safety Officer), Pauline de Jong (Chief Conservation Officer) and Michael Martin (Safety Officer).

#### Documents Requested/ Collected:

Photos and notes taken on site.

**Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.**

Michael Martin S-004 / Brian Heppelle S-001/Pauline de Jong C-002

Inspected By



Signature of OROGO Chief Safety Officer

2019-12-20

Date Signed



Photo # 1: Well Site



Photo #2: Rusted metal debris scattered around site is a safety hazard. Debris should be removed from site