

<b>Incident #</b>	INC-2022-001-IKHIL-OA-2520-2620	
<b>Incident occurred on:</b>	April 13, 2022	
<b>OA/ACW #:</b>	ACW-2018-009	
<b>Operator:</b>	Utilities Group Facilities Inc. (UGFI)	
<b>Location:</b>	Ikhil Facilities – Shop (Gwich'in Settlement Area)	
<b>Summary of incident:</b>	Snowmobile collision while loading – No Injury	
<b>Incident reported to OROGO by the operator on:</b>	June 6, 2022	
<b>Incident reported to NT-NU Spill Line (if required) on:</b>	N/A	
<b>Operator Follow-up Investigation Report (if required):</b>	N/A	
<b>Status:</b>	<p><b>June 9, 2022:</b> UGFI identified a list of incidents to date in the 2022 calendar year.</p> <p><b>DETAILS:</b> A trailer had two snowmobiles on it facing forward. To fit a third sled on the trailer it had to be loaded backwards (rear facing). During loading, the third snowmobile was in reverse and the employee's mitt was caught in the handle bar gauntlet which caused the throttle to open more than planned. This snowmobile hit another snowmobile on the trailer bending the tow bar breaking the taillight.</p> <p><b>CORRECTIVE ACTION:</b> Personnel were cautioned to take more care when loading and unloading snowmobiles and to ensure both hands are on the handlebar. It was also decided, and relayed to staff, that bar gauntlets are to be pulled back to allow clear access to the throttle and breaks while loading and unloading any snow machine.</p> <p>This incident does not meet the requirements to file a follow up investigation report under s. 75(2)(b) of the <i>Oil and Gas</i></p>	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.



NWT OFFICE OF THE REGULATOR OF OIL AND GAS OPERATIONS

## INCIDENT STATUS REPORT

	<p><i>Drilling and Production Regulations.</i></p> <p>No Further Action Required</p> <p><b>File Closed – June 13, 2022</b></p>
<b>Completed By:</b>	Michael Martin – Chief Safety Officer

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.