

Rhonda Miller - MVLWB

From: Wayne Starling [Wayne.Starling@inac-ainc.gc.ca]
Sent: July-07-11 1:04 PM
To: Affairs Manager, Intergovernmental; Arsenault, Jeanne; bblack@fortsmith.ca; Carolc.lands@gmail.com; ceo@srfn195.com; Coe, Charlene; darnelle.mccurdy@inac.gc.ca; DIEP_DUONG@gov.nt.ca; doraenzoe@yahoo.com; Duane_Fleming@gov.nt.ca; ec.ea.nwt@ec.gc.ca; environment@ykdene.com; esangris@ykdene.com; fortsmithmetiscouncil@northwestel.net; Frmc53@yahoo.ca; GERALD_ENNS@gov.nt.ca; Glen_Mackay@gov.nt.ca; Gnwt_ea@gov.nt.ca; Gordon.Hamre@pc.gc.ca; hrnc@northwestel.net; ima.nwtmn@northwestel.net; imadenegurl@hotmail.com; jane.fitzgerald@ec.gc.ca; jbrennan@yellowknife.ca; Jenkins, Robert; jsoucy@fortsmith.ca; K_Johnson@gov.nt.ca; Katherine.Cumming@pc.gc.ca; lands@nsma.net; landsnresources@katlodeeche.com; Lawrance, James; Imandeville@denenation.com; Mark_Davy@gov.nt.ca; mary.kelly@ec.gc.ca; mrichardson@hayriver.com; MVLWB, Lynn Boettger -; Norris, Angela; Patrick_Clancy@gov.nt.ca; permits@mvlwb.com; Rhonda_Batchelor@gov.nt.ca; Rick.Walbourne@dfo-mpo.gc.ca; rlong@yellowknife.ca; Sao_enterprise@northwestel.net; sarahlacey.mcmillan@ec.gc.ca; scellis@eastarm.com; screeningofficer@eastarm.com; Seale, Lorraine; Spence, Matthew; Stewart, Scott; Support Unit, Consultation; SusanA@wcb.nt.ca; tslack@ykdene.com; ttsetta@ykdene.com; Witherly, Kate; wpfm@northwestel.net
Cc: Graham', 'Kathleen; MVLWB', 'Amanda Gauthier -; Racher', 'Kathy; zabey@mvlwb.com
Subject: re: MV2011L3-0001 - Fort Smith Type A Renewal Additonal Information and Technical Memorandum
Attachments: ATT00017.gif

Hello Lynn:

Thank you for sending these documents. I just have one comment and that is regarding Section 4 and the calculation of the mixing zone. Golder said they based their calculation on a river width of 290 Metres which severely under represents the actual channel width. At the sewage lagoon outfall the Slave River is approx. 1.5 Km wide and narrows in places to about a Kilometer, but nowhere is it as narrow as 290 Metres. I will fax you a copy of a 1:50,000 scale map of the area for your reference, and since the initial measurement is significantly off I recommend that the mixing zone be re-calculated using a more precise channel width. Hope this is useful, and sorry for the late submission.

Regards,

Wayne

>>> "Lynn Boettger - MVLWB" <lboettger@mvlwb.com> 7/6/2011 11:25 am >>>
Hi All –

Please find attached a Technical Memorandum on the development of Effluent Quality Criteria from Golder Associates as well as some additional information on the Town of Fort Smith Landfill. These documents can also be found on the on-line public registry.

Note that interventions are due at or before 5 pm today. We recognize that some of this material has come in last minute and may not be able to be included in your intervention. Please be prepared with any comments and/or questions on this material for the public hearing.

Thanks,
Lynn

Lynn Boettger
Regulatory Officer

Mackenzie Valley Land and Water Board
7th Floor, 4922 48th St, PO Box 2130 | Yellowknife, NT | X1A 2P6
ph 867.669.0506 | direct 867.766.7469 | fax 867.873.6610
lboettger@mvlwb.com | www.mvlwb.com

