

August 19, 2021

Joseph Mackenzie
Chair
Wek'èezhii Land and Water Board
#1, 4905-48th Street
Yellowknife, NT
X1A 3S3

Jamie Steele
North Slave Regional Office
Department of Lands
Government of the Northwest Territories
#16 Yellowknife Airport
Yellowknife, NT
X1A 3T2

Subject: W2016D0003: Spill 2021344 Report

Pursuant to Part C Condition 18(c) of Land Use Permit W2016D0003, Arctic Canadian Diamond Company Ltd. (Arctic) is providing a detailed report on Spill 2021253 which occurred August 13, 2021 at the Sable Development.

Summary

At 11:45 on August 13, 2021 approximately 120 L of steering hydraulic fluid spilled beneath the 793 Haul Truck in the Sable truck parking area. The location of the spill was:

Lat: 64.860209
Long: -110.524435

Root Cause

The spill was determined to be caused by a steering hose rupture on the 793 Haul Truck.

Immediate Action Taken

The hydraulic steering fluid spilled beneath the haul Truck was immediately cleaned up (clean-up Completed August 14). The spill was reported to the Environment Department and subsequently reported to the GNWT Inspector.

Follow Up Action Taken

The haul truck was moved and the spill beneath the unit was cleaned up. Site Services excavated the area and approximately three IT-28 buckets of contaminated material was disposed of at the Land farm at Main Camp (approximately 6 m³). The spill was completely cleaned up by August 14, 2021. The Environment Department inspected the area to confirm that no hydraulic oil staining remained.

Figure 1. Spill 2021344 before clean-up



Figure 2. Spill 2021344 after clean-up



We trust this report is clear and informative. If you have any questions or comments, please contact the undersigned at Todd.Swenson@arcticcanadian.ca or (867) 880-4400 ext. 2293.



Arctic Canadian Diamond Company Ltd.

900-606 4 Street SW (403) 910-1933
Calgary, Alberta T2P 1T1 (403) 910-1934 fax

Yours Sincerely,

A handwritten signature in black ink, appearing to read "Todd Swenson".

Todd Swenson
Sr. Environment Advisor – Environmental Operations
Arctic Canadian Diamond Company Ltd.