

May 15, 2022

Mr. Mason Mantla Chair
Wek'èezhii Land and Water Board
#1, 4905-48th Street
Yellowknife, NT
X1A 3S3

Jamie Steele
North Slave Regional Office
Department of Lands
Government of the Northwest Territories
#16 Yellowknife Airport
Yellowknife, NT
X1A 3T2

Subject: W2016D0003: Spill 2022170 Report

Pursuant to Part C Condition 18(c) of Land Use Permit W2016D0003, Arctic Canadian Diamond Company Ltd. (Arctic) is providing a detailed report on Spill 2022170 which occurred on May 07, 2022, at the Sable Development.

Summary

At 3:47 PM on May 7, 2022, 150 L of hydraulic oil spilled onto disturbed ground in Sable Development. The location of the spill was: Sable Pit 422 Bench.

Lat: 64.861341
Long: -110.514776

Root Cause

3754 Loader's O-ring failed on the right bucket tilt line.

Immediate Action Taken

The operator immediately deployed spill pads which absorbed the hydraulic oil.

Follow Up Action Taken

On May 10, 2022, heavy equipment scaped up impacted material in preparation for loading and hauling. Impacted material was then hauled and dumped in a suitable disposal area (Panda/Koala Zone S).



Arctic Canadian Diamond Company Ltd.

900-606 4 Street SW (403) 910-1933
Calgary, Alberta T2P 1T1 (403) 910-1934 fax

We trust this report is clear and informative. If you have any questions or comments, please contact the undersigned at Jonah.Kelly@arcticcanadian.ca or (867) 880-4400 ext. 2293.

Yours Sincerely,

A handwritten signature in black ink, appearing to read "Jonah Kelly", is written over a circular stamp or seal.

Jonah Kelly
Environment Advisor – Environmental Operations
Arctic Canadian Diamond Company Ltd.