



Dominion Diamond Mines ULC
900-4920 52 Street
Yellowknife, NT X1A 3T1 (867) 669-6100
www.ddmines.com

July 30, 2019

Jamie Steele, Resource Management Officer
North Slave Regional Office
Department of Lands
Government of the Northwest Territories
#16 Yellowknife Airport
Yellowknife, NT X1A 3T2

Joseph Mackenzie, Chair
Wek'èezhii Land and Water Board
#1, 4905-48th Street
Yellowknife, NT X1A 3S3

RE: W2018C0005 – Additional Portable Reverse Circulation (PRC) Holes on Ekati Leases

Dominion Diamond ULC (Dominion) submits this notification under Part C, Condition (2) of Land Use Permit (LUP) W2018C0005 of three additional diamond drill on the Ekati mine leases. These holes are in addition to previous submitted diamond drill holes (July 18, 2019). Please note that Dominion has chosen to either postpone or cancel the following holes D16-AA18, D10-AA4, D15-BA27, and Tri Hump Lake. These holes were submitted with the July 18, 2019 notification.

All operations will be helicopter supported and based out of Ekati. The target location of these holes is shown in the plan below, along with planned coordinates. We anticipate starting on these holes on or before August 9, 2019.

Sincerely,

A handwritten signature in blue ink that reads 'R. Woodward'.

Rick Woodward
Superintendent – Exploration



Dominion Diamond Mines

Dominion Diamond Mines ULC

900-4920 52 Street

Yellowknife, NT X1A 3T1

(867) 669-6100

www.dmines.com

Drillhole Name	Easting	Northing	Elevation	Azimuth	Dip	Target Depth
D9-BA53 (Alpaca)	543546	7175045	450	222	-55	200
D9-BA58 (Okapi)	543038	7174919	450	298	-55	200
D16-DA41	543638	7183995	450	285	-45	500

