
From: Meg McCluskie <Meg_McCluskie@gov.nt.ca>
Sent: September 14, 2022 11:02 AM
To: Anneli Jokela <ajokela@wlwb.ca>
Cc: Denise Lockett <dlockett@nighthawkgold.com>; Wendy Bidwell <Wendy_Bidwell@gov.nt.ca>; Bruno Croft <Bruno_Croft@gov.nt.ca>
Subject: W2018L2-0003 - Nighthawk Gold Corp. - Indin Lake Gold Property

Good morning Anneli,

On 9 September 2022, I inspected SNP station 5-10 of the Indin Lake Gold Property. The depression at this location has been adequately infilled and therefore I recommend that SNP station 5-10 be removed from the Surveillance Network Program for Water License W2018L2-0003. At the time of this inspection, water quality at SNP stations downstream of the depression met Effluent Quality Criteria described in Conditions Applying to Waste Disposal (Part G: 3.b). Nighthawk Gold Corp. will continue to monitor water quality on site, as per the sampling schedule described in their water license.

If you have any questions or require more information, please contact me.

Thanks,

Meg

Related documents:

[Nighthawk – request for SNP Change](#)
[WLWB response requiring approval from Inspector](#)

Mársi | Kinanaskomitin | Thank you | Merci | Hą́ı' | Quana | Qujannamiik | Quyanainni | Máhsı | Máhsı | Mahsi
Meg McCluskie

Water Resource Officer
North Slave Region
Department of Environment and Natural Resources
Government of the Northwest Territories

3803 Bretzlaff Drive
PO Box 2668
Yellowknife, NT X1A 2P9

-Phone: 867-767-9238 ext.53244

-Cell: 867-446-5680

-Fax: 867-873-6230

www.gov.nt.ca