

From: [Karine Gignac](#)
To: [Garry Snyder](#)
Cc: [Clint Ambrose](#); [Christopher Babkirk](#); [Gaurav Kaushish](#); [Jamie Hynes](#); [Wayne Thompson \(wt.drayton@gmail.com\)](#); [Anneli Jokela](#); [Roberta Judas](#); [Alexis Campbell](#); [Trevor Bryce](#); [Ronald Schaub \(rschaub@rowes.ca\)](#); [Robert Osborne](#)
Subject: RE: W21F010 Wekweèti inspection report 24 Feb 2022
Date: March 2, 2022 3:57:15 PM

Thank you Garry for providing an up-date on the items requiring action.

Have a great day!

Karine

From: Garry Snyder
Sent: March 1, 2022 9:42 AM
To: Karine Gignac
Cc: Clint Ambrose; Christopher Babkirk; Gaurav Kaushish; Jamie Hynes; Wayne Thompson (wt.drayton@gmail.com); Anneli Jokela (ajokela@wlwb.ca); Roberta Judas (rjudas@wlwb.ca); Alexis Campbell; Trevor Bryce; Ronald Schaub (rschaub@rowes.ca); Robert Osborne
Subject: RE: W21F010 Wekweèti inspection report 24 Feb 2022

Good morning Karine,

Thank you for providing us with your Feb. 24th, 2022 Inspection report.

At this time our contractor Tlich Management Services has informed me that all hydrocarbon spill's the Inspector noted in the report from P208 south have been appropriately cleaned with the contaminated snow being properly disposed of. TMS is waiting for confirmation from the Rowes Crew regarding the spills at P223 where their active camp is currently located.

Feel free to contact me with any questions or concerns.

Thank you,
Garry

Chris / Rob,

Other than hydrocarbon spills that needed to be cleaned; the Inspector has identified the following concerns.

Please provide an update if these items listed below have been appropriately addressed, or if not when they will be completed?

1. Laydown Area (demobilized camp) P13 km 0
 - a. Ensure that drip trays are used under all parked equipment.
 - i. See Grader in Figure 7

- ii. Ensure there a wrap around the leaking ram on the grader until it has been repaired.
 - b. Daily checks to ensure any new leaks are immediately cleaned up and noted in the spill log.
- 2. Demobilized Camp – P208
 - a. Regular monitoring of location and immediately clean any new leaks noted as solar load increases.
 - b. Fig 8 & 9
- 3. Active Camp (P223)
 - a. Confirm all hydrocarbon leaks have been cleaned up with the contaminated snow properly disposed of.
 - b. Camp Generator
 - i. Requires a spill kit of appropriate size. (Fig 12)
 - c. Fuel Vaults
 - i. Requires a spill kit of appropriate size. (Fig 13)
 - ii. Available drip trays in place and must be used during refuelling activities. (Fig 14)
 - d. Pick-up Truck Fuel Nozzle
 - i. Available drip tray in place and must be used during refuelling activities. (Fig 15)
 - e. Parked Equipment – Water Truck
 - i. Requires drip trays under all equipment. (Fig 17)
 - ii. Additional trays required where leaks are noted, repairs to be completed ASAP. (Fig 18)
 - f. Fuel Barrels
 - i. Secondary containment is required
 - ii. Fig 19
 - g. Spill Kits
 - i. Visible locations
 - ii. Easy to Access

Feel free to contact me with any questions or concerns.

Thank you,
Garry

Mársi | Kinanaskomitin | Thank you | Merci | Háj' | Quana | Qujannamiik | Quyanainni | Máhsı | Máhsı | Mahsi

Garry Snyder

Project Officer
North Slave Regional Office
Department of Infrastructure
Government of the Northwest Territories

Phone: (867) 767-9089 Ext.31191

Cell: (867) 445-5524

www.gov.nt.ca

From: Karine Gignac
Sent: February 28, 2022 2:22 PM
To: Robert Osborne; Garry Snyder
Cc: Clint Ambrose; Christopher Babkirk; Gaurav Kaushish; Jamie Hynes; Wayne Thompson (wt.drayton@gmail.com); Anneli Jokela (ajokela@wlwb.ca); Roberta Judas (rjudas@wlwb.ca); Alexis Campbell; Trevor Bryce; Ronald Schaub (rschaub@rowes.ca)
Subject: RE: W21F010 Wekweeti inspection report 24 Feb 2022

Perfect thank you Rob,

I will have it added to the file

Karine

From: Robert Osborne [mailto:ROsborne@tlichoc.com]
Sent: February 28, 2022 2:16 PM
To: Karine Gignac; Garry Snyder
Cc: Clint Ambrose; Christopher Babkirk; Gaurav Kaushish; Jamie Hynes; Wayne Thompson (wt.drayton@gmail.com); Anneli Jokela (ajokela@wlwb.ca); Roberta Judas (rjudas@wlwb.ca); Alexis Campbell; Trevor Bryce; Ronald Schaub (rschaub@rowes.ca)
Subject: RE: W21F010 Wekweeti inspection report 24 Feb 2022

EXTERNAL: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender's name and email address and know the content is safe.

Hello Karine,

I attached the KBL Bill of Lading showing that the contaminated snow from the spill clean-up was disposed of properly.

Regards,

Rob Osborne, STS

Project Coordinator

Mobile: (867) 445-8670

Phone: (867) 766-4909

Website: www.tlichoc.com

From: Karine Gignac <Karine_Gignac@gov.nt.ca>
Sent: February 28, 2022 1:33 PM
To: Garry Snyder <Garry_Snyder@gov.nt.ca>
Cc: Clint Ambrose <Clint_Ambrose@gov.nt.ca>; Christopher Babkirk <cbabkirk@tlicheic.com>; Gaurav Kaushish <GKaushish@tlicheic.com>; Jamie Hynes <Jamie_Hynes@gov.nt.ca>; Robert Osborne <ROsborne@tlicheic.com>; Wayne Thompson (wt.drayton@gmail.com) <wt.drayton@gmail.com>; Anneli Jokela (ajokela@wlwb.ca) <ajokela@wlwb.ca>; Roberta Judas (rjudas@wlwb.ca) <rjudas@wlwb.ca>; Alexis Campbell <Alexis_Campbell@gov.nt.ca>; Trevor Bryce <tbryce@tlicheic.com>; Ronald Schaub (rschaub@rowes.ca) <rschaub@rowes.ca>
Subject: W21F010 Wekweeti inspection report 24 Feb 2022

Good afternoon,

Please find attached the report for the 24th February 2022 inspection of the former and active campsite along the Wekweeti Winter Road.

Do not hesitate to reach out to the undersigned, should you have any questions.

Regards,

Karine Gignac

Resource Management Officer II
North Slave Regional Office
Department of Lands
Government of Northwest Territories
140 Bristol Avenue, Yellowknife, NT, X1A 3T2
Tel: 867-767-9187 ext 24189
Email: karine_gignac@gov.nt.ca

From: Garry Snyder
Sent: February 26, 2022 2:19 PM
To: Christopher Babkirk
Cc: Clint Ambrose; Robert Osborne; Karine Gignac; Gaurav Kaushish; Jamie Hynes
Subject: Re: Winter Road cleanup

Sounds good, thanks Chris.

Garry

Sent from my iPhone

From: Christopher Babkirk [mailto:cbabkirk@tlicheic.com]
Sent: February 26, 2022 2:13 PM
To: Clint Ambrose
Cc: Robert Osborne; Garry Snyder; Karine Gignac; Gaurav Kaushish; Jamie Hynes
Subject: Re: Winter Road cleanup

I specifically asked about this ram leaking. It was confirmed the contaminated snow directly below

was removed.

Sent from my iPhone

From: Clint Ambrose
Sent: February 26, 2022 12:08 PM
To: Robert Osborne; Garry Snyder
Cc: Karine Gignac; Christopher Babkirk; Gaurav Kaushish; Jamie Hynes
Subject: RE: Winter Road cleanup

Appreciate the clean-up and photos.

Thanks Rob.

Regards,

Clint

Clint Ambrose
Manager, Resource Management
(867) 446-0769

From: Garry Snyder
Sent: February 26, 2022 12:08 PM
To: Robert Osborne
Cc: Clint Ambrose; Karine Gignac; Christopher Babkirk; Gaurav Kaushish; Jamie Hynes
Subject: Re: Winter Road cleanup

Good morning Rob,

Thank you for the update and promptly getting the crews to clean up the hydrocarbon and glycol spills.

Thank you for providing pictures. I'm sure this is a foolish question, but I don't see a picture of the cleaned area below the hydronic steering ram on the water truck plow frame?

I see the spill pad wrapped on the ram. Do you have one that includes the ram & cleaned area together?

Please have the crews continue to regularly monitor the plow truck area for additional potential minor spills until it is repaired or removed for repairs

Thank you,
Garry.

Sent from my iPhone

From: Robert Osborne [mailto:ROsborne@tlchoic.com]
Sent: February 26, 2022 11:40 AM
To: Garry Snyder

Cc: Clint Ambrose; Karine Gignac; Christopher Babkirk; Gaurav Kaushish; Jamie Hynes
Subject: Winter Road cleanup

EXTERNAL: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender's name and email address and know the content is safe.

Hello Garry,

We talked about this yesterday but I now have the photos you asked for.
Yesterday TEES cleaned up the brush pile at km 8. It was spread around in the adjacent woods.
The spills and diesel-stained snow at Portage 208 were cleaned up.
The leaking boom on the plow truck was wrapped with spill pads and the spill was cleaned up.
A spill was cleaned up at Gameti Junction.
All of the contaminated snow/ice was bagged up for offsite disposal.

Regards,

Rob Osborne, STS

From: Garry Snyder
Sent: February 25, 2022 12:20 PM
To: Clint Ambrose
Cc: Jamie Hynes; Robert Osborne (ROsborne@tlicheic.com); Trevor Bryce (tbryce@tlicheic.com); Christopher Babkirk (cbabkirk@tlicheic.com); Karine Gignac; Wayne Thompson (wt.drayton@gmail.com); Ron Schaub
Subject: RE: Inspection Findings - Wekweètì Winter Road - Land Use Permit: W2021F0010 - Spill Clean-Up and Mining of Snow

Good morning Clint,

Thank you for providing us with your inspection report.

As the Inspector has already discussed with Rowes your concerns with the mining of snow from vegetated areas I'll consider this line item completed.

It's unfortunate and a little frustrating to be informed of several small hydrocarbon spills you have identified that require cleaning.

Christopher / Rob,

As per Clint's concerns please provide us with a response to this email, including the following information ASAP:

1. **Date that TMS will be cleaning the hydrocarbon spills at P13, P208, P209, and P223.**
2. Confirmation that the hydrocarbon spills have been cleaned.
3. Photographs of before and after each identified spill is appropriately cleaned.
4. Confirmation of off-site disposal of all impacted snow.

Thank you,
Garry

Mársi | Kinanaskomitin | Thank you | Merci | Hq̓i' | Quana | Qujannamiik | Quyanainni | Máhsı | Máhsı | Mahsi

Garry Snyder
Project Officer
North Slave Regional Office
Department of Infrastructure
Government of the Northwest Territories

Phone: (867) 767-9089 Ext.31191

Cell: (867) 445-5524

Fax: (867) 873-0257

www.gov.nt.ca

From: Clint Ambrose

Sent: February 25, 2022 10:08 AM

To: Garry Snyder

Cc: Jamie Hynes; Robert Osborne (ROsborne@tlicheic.com); Trevor Bryce (tbryce@tlicheic.com); Christopher Babkirk (cbabkirk@tlicheic.com); Karine Gignac; Wayne Thompson (wt.drayton@gmail.com); Ron Schaub

Subject: Inspection Findings - Wekweèti Winter Road - Land Use Permit: W2021F0010 - Spill Clean-Up and Mining of Snow

Good morning Garry,

We conducted an inspection of the Contractor's campsites and with the exception of small spills to clean-up at the Km 0 laydown, the P208 Campsite and the P223 Campsite, no major concerns were noted during the inspection.

The spills at the P208 campsite were marked by Inspectors and it is anticipated that a thorough clean-up with proper off-site disposal of all impacted snow occurs in a timely manner. Please provide photographs of the clean-up to confirm compliance.

One other concern discussed with the Rowe's Snowcat Operator was the mining of snow from the shoreline of a watercourse. As seen in IMG 6784, a minor amount of disturbance to ground surface from the blades of equipment was observed. To prevent further damage as this operation progresses, the Contractor should only be mining snow from the ice surface of lakes and not vegetated areas.

No remediation is required of this area, but practices changed to prevent a re-occurrence.

Inspectors appreciate that the concerns will be addressed in a timely manner.

Regards,

Clint

Clint Ambrose
Manager, Resource Management (Inspector)
North Slave Regional Office
Department of Lands
Government of Northwest Territories
140 Bristol Avenue, Yellowknife, NT X1A 3T2
Cell: (867) 446-0769 / Tel: (867) 767-9188
Email: clint_ambrose@gov.nt.ca
Web: www.lands.gov.nt.ca