



NWT OFFICE OF THE REGULATOR OF OIL AND GAS OPERATIONS

Office of the Regulator of Oil and Gas Operations

P.O. Box 1320, Yellowknife, NT X1A 2L9

Tel: 867-767-9097 • Fax: 867-920-0798 • Web: www.oro.gov.nt.ca

Courier Address: 4th floor, 5201 – 50th Avenue, Yellowknife, NT X1A 3S9

Mr. Lloyd Doyle
Corporate Operating Officer
Paramount Resources Ltd.
4700 Bankers Hall West
888 3 STREET SW
CALGARY AB T2P 5C5

December 7, 2016

Dear Mr. Doyle

Information Request No. 1: Paramount Resources Ltd. (Paramount) Application for Approval to Abandon the Fort Liard O-35 Well (well ID 1868) (ACW-2016-004)

Further to the Paramount Resources Ltd. application dated November 21, 2016, for approval to abandon the Fort Liard O-35 well, the Office of the Regulator of Oil and Gas Operations (OROGO) requires additional information as set out in the attached Information Request No. 1.

Please submit your response on or before 4:00 p.m., Thursday, December 15, 2016 or contact OROGO if you are unable to respond within this timeframe. Please send your written responses and any associated correspondence to Mr. James Fulford, Chief Conservation Officer, OROGO.

Should you have any questions, please contact me at 867-767-9097.

Sincerely,

Brian Heppelle
Senior Advisor, Technical

Attachment

C. Mr. Patrick Kelly, Paramount Resources Ltd.

Mr. Dick Heenan, Heenan Energy Services Ltd.

Bureau de l'organisme de réglementation des opérations pétrolières et gazières

B.P. 1320, Yellowknife, TNO X1A 2L9

Tél : 867-767-9097 • Téléc : 867-920-0798 • Site web : www.oro.gov.nt.ca

Adresse de messagerie : 4^e étage, 5201 – 50^e Avenue, Yellowknife TNO X1A 3S9



BUREAU DE L'ORGANISME DE RÉGLEMENTATION DES OPÉRATIONS PÉTROLIÈRES ET GAZIÈRES DESTNO

Information Request No. 1
Application to Alter the Condition of a Well
Abandonment of the Fort Liard O-35 Well (well ID 1868)
ACW-2016-004

- 1) ***Please provide a copy of the Well History Report for well operations conducted in 2009.***
- 2) ***The abandonment program proposes to leave in place a permanent bridge plug at 50mKB. With the bridge plug left in place at 50mKB, please describe how Paramount will confirm that there is no casing pressure below the bridge plug and, consistent with industry best practices, how the entire wellbore from the zonal abandonment at 1355mKB is vented to surface.***
- 3) ***Please provide confirmation that there is no gas migration or surface casing vent flow associated with the Fort Liard O-35 well.***