

<b>Incident #</b>	INC-2023-001-SOG-OA-2018-003	
<b>Incident occurred on:</b>	January 6, 2023	
<b>OA/ACW #:</b>	OA-2018-003	
<b>Operator:</b>	Strategic Oil and Gas Ltd.	
<b>Location:</b>	H-03 Battery	
<b>Summary of incident:</b>	Worker struck by pressurized hose	
<b>Incident reported to OROGO by the operator on:</b>	January 6, 2023	
<b>Incident reported to NT-NU Spill Line (if required) on:</b>	N/A	
<b>Operator Follow-up Investigation Report:</b>	Due: January 27, 2023 Received: January 25, 2023	
<b>Status:</b>	<p><b>January 6, 2023:</b> Contractors for Strategic Oil and Gas Ltd. reported a worker hit by a pressurised hose from the Combo Vac at the H-03 battery in Cameron Hills The worker was evaluated by the medic and was sent to the High level for medical treatment.</p> <p><b>January 9, 2022:</b> Contractors for Strategic Oil and Gas Ltd. provided OROGO with their initial investigation report.  The worker returned to work the same day.</p> <p><b>January 25, 2023:</b> OROGO received the required Investigation report for this incident as required by Section 75 of the <i>Oil and Gas Drilling and Production Regulations</i>.  The report identified the worker failed:</p> <ol style="list-style-type: none"> <li>1. Identify risks;</li> <li>2. Failed to check the lines were depressurized; and</li> <li>3. Failed to identify improper body positioning.</li> </ol>	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.



NWT OFFICE OF THE REGULATOR OF OIL AND GAS OPERATIONS

## INCIDENT STATUS REPORT

	<p>Procedural review and competency assessment was conducted with the worker on proper operation of the Comb Vac on January 16, 2023. Safeguards in place to verify lines are depressurized prior to disconnection.</p> <p>No further action required.</p> <p><b>FILE CLOSED – February 6, 2023</b></p>
	<p>Michael Martin – Chief Safety Officer</p>

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.