



Telephone: 867 777-8900

Fax: 867-777-2090

September 22, 2016

Chinook Energy Inc.
Suite 1000, 517-10th Avenue SW
Calgary, AB T2R 0A8

Attention: Darren Tomecek

File Number	G2002A0013
Type of Operation	OIL AND GAS DRILLING - WELLSITE
Location	N73 sump

To: Darren Tomecek,

An inspection of the above noted operation was conducted on September 21, 2016 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Conrad Baetz, Superintendent Beaufort Delta Region, Dept. of Lands
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Chinook Energy Inc.	Permit Expiry Date:	December 31, 2005
Land Use Permit No.	G2002A0013	Previous Inspection:	September 09, 2014
Quarrying Permit No.		Inspection Date:	September 21, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	N73 sump		
Current Stage of Operation:	completed and restored		
Program Modifications Approved:	nil		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	N73				
Location as Permitted	A				
Time as Permitted	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

N73:

During the inspection it was observed that the sump continued to have 70 to 75 % vegetation cover from previous inspection dated Sept. 10 2014. Further monitoring will be continued to observe the vegetation cover, also a final plan will be required and once received a final inspection will be conducted.

MATTERS FOR FOLLOW UP

check vegetation cover and await final plan.

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial of N73



Figure 2

Aerial of N73





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Aerial of N73




Figure 4
Aerial of N73

