



Telephone: 867 777-8900

Fax: 867-777-2090

June 7, 2016

GNWT Department of Transportation
P.O. Box 2038
Inuvik, NT X0E 0T0

Attention: Arvind Vashishtha

File Number	G10Q009
Type of Operation	QUARRY SITE - Existing
Location	Km 34

To: Arvind Vashishtha,

An inspection of the above noted operation was conducted on June 06, 2016 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Conrad Baetz, Superintendent Dept of Lands, Beaufort Delta Region
GLWB

Bag Service #1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Transportation	Permit Expiry Date:	December 06, 2017
Land Use Permit No.	G10Q009	Previous Inspection:	June 18, 2013
Quarrying Permit No.		Inspection Date:	June 06, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 34		
Current Stage of Operation:	active		
Program Modifications Approved:	LUP extended to Dec. 06 2017, also a new QP for 500 m ³		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	KM 34 of the Dempster Highway				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Erosion (Control or Prevention)	A				
Restoration of Lands	A				
Permits	A				
Facilities	A				
Chemicals	A				
Matters not Inconsistent	A				

Explanatory Remarks -

KM 34 of the Dempster Highway:

A pre site inspection was conducted at the source. Please note that at the time of the inspection all aspects were satisfactory, it is recommended that both Terms and Conditions of the L.U.P. and Quarry Permits are adhered too.

Please advise on when the 500 m³ will be removed from the location as per condition 26(1)(b) item number 7(a) Reports Before Removal.

MATTERS FOR FOLLOW UP

condition 26(1)(b) item number 7(a) Reports Before Removal.

N/A
Representative Signature

[Signature]
Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1
km 34



Figure 2
km 34





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Km 34



Figure 4



Date:	June 06, 2016	Permit #:	G10Q009	Page No:	3
-------	---------------	-----------	---------	----------	---