



Beaufort Delta Region
 Bag Service #1
 Inuvik, NT X0E 0T0

Telephone: 867 777-8900
 Fax: 867-777-2090

April 17, 2014

GNWT Department of Transportation
 P.O. Box 2033

Inuvik, NT X0E 0T0

Attn: Arvind Vashishtha

RE: Land Use Permit G13H004
 Fuel Storage, Camp and Land Farm
 James creek

To: Arvind Vashishtha,

An inspection of the above noted operation was conducted on April 16, 2014 by the undersigned.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,



Donald Arey
 Manager, Resource Management
 Department of Lands
 Beaufort Delta Region

Cc: **GLWB**

containment.
 As result of the above, the Fuel Containment is also in non-compliance with Condition # 26(1)(g) item 23:
Fuel Containment: The Permittee shall not allow petroleum products to spread to surrounding lands or Watercourses.
 Please note that these items are repetitive in previous inspections. It is also recommended that the Terms and Conditions be reviewed with the contractors and operators of the site.

N/A
 Representative Signature

[Signature]
 Inspector's Signature

Date:	April 16, 2014	Permit #:	G13H004	Page No:	1
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Transportation	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	August 20, 2013
Quarrying Permit No.		Inspection Date:	April 16, 2014
Contractor:		Subcontractor:	
Location(s) Inspected:	James creek		
Current Stage of Operation:	on-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected		
	Fuel Storage	Camp	Land-Farm
Chemicals	U		N/I
Ecological Resources	A		N/I
Equipment as Approved (Type & Size)	A	A	
Erosion (Control or Prevention)		A	N/I
Facilities	A	A	N/I
Fuel Storage	U		
Historical / Archaeological Sites			N/I
Location as Permitted	A	A	N/I
Matters not Inconsistent	A	A	N/I
Methods & Techniques	A	A	N/I
Permits	A	A	N/I
Restoration of Lands			N/I
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A	N/I
Time as Permitted	A	A	N/I
Wastes		A	
Wildlife and Fisheries Habitat (Protection)			N/I

Explanatory Remarks -

Land-Farm: The Land farm was not inspected as result of snow cover.

Camp: All were satisfactory at time of inspection

Fuel Storage:

James Creek Fuel Storage: During this inspection it was observed that the waste oil behind garage stacked by building does not have secondary containment and is in non-compliance with Condition # 26(1)(g) item 10 :

Waste Petroleum Disposal: The Permittee shall dispose of all combustible waste petroleum products by removal to an approved disposal facility.

Also observed was no secondary Containment for the Refuelling area and is in non-compliance with Condition # 26(1)(m) item 22:

Secondary Containment - Refuelling: The Permittee shall set up all refueling points with secondary containment.

As result of the above, the Fuel Containment is also in non-compliance with Condition # 26(1)(g) item 23:

Fuel Containment: The Permittee shall not allow petroleum products to spread to surrounding lands or Watercourses.

Please note that these items are repetitive in previous inspections. It is also recommended that the Terms and Conditions be reviewed with the contractors and operators of the site.

N/A

Representative Signature

[Signature]

Inspector's Signature

ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Image 1

No secondary containment at refueling point



Figure 2

No secondary containment at refueling point




Figure 3
waste petroleum



Figure 4
waste petroleum

