



North Mackenzie District
P.O. Box 2100
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

RECEIVED
AUG 29 2013

August 21, 2013

GNWT Department of Transportation
P.O. Box 2038
Inuvik, NT X0E 0T0

Attn: Arvind Vashishtha

RE: Land Use Permit G13H004
FUEL CACHES

To: Arvind Vashishtha,

An inspection of the above noted operation was conducted on August 20, 2013 by Resource Management Officer Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Conrad Baetz,
Manager, North Mackenzie District

Cc: **GLWB**

Representative Signature

Inspector's Signature

ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Transportation	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	New
Quarrying Permit No.		Inspection Date:	August 20, 2013
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 14.2 James Creek		
Current Stage of Operation:	active		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Fuel Storage and site				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	U				
Fuel Storage	U				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Sections 12 to 19 T.L.U.R.	A				

Explanatory Remarks -

Fuel Storage and site:

It was observed that the fuel refueling area does not have any secondary containment. This has been pointed out in past inspections again no secondary containment for the refuel area is observed.

Condition # 22 - Secondary Containment – Refueling

The Permittee shall set up all refueling points with secondary containment.

It was also observed that there is debris in front of the garage by the roads edge and as well behind the garage by hillside a caribou skin and debris.

condition # 6 - Clean Work Area

The Permittee shall ensure that the land use area is kept clean at all times.

As the Permit Holder it is recommended to ensure that employee's are made aware of and abide to the Terms and Conditions of your permit and actions be taken to resolve the unsatisfactory concerns.


 Representative Signature


 Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Fuel tank refuel area – No secondary Containment



Figure 2

Fuel tank refuel area - No secondary Containment



Figure 3



ENVIRONMENTAL INSPECTION REPORT

Figure 3
debris by road edge



Figure 4
debris behind shop

