



Telephone: 867 777-8900

Fax: 867-777-2090

August 11, 2017

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT XOE OT0

Attention: Arvind Vashishtha

File Number G13H004
Type of Operation FUEL CACHES
Location Km 14.2 James Creek

To: Arvind Vashishtha ,

An inspection of the above noted operation was conducted on August 10, 2017 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

The unsatisfactory observations made to the site are again being repetitive observations. It is the permit holders responsibility to ensure that the Terms and Conditions of the Permit are to be followed and should not be continually reminded that it is their responsibility of such.

If you have any questions, please contact me at 867 777-8900.

Sincerely,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Dept of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF July 19, 2017

Ensure items identified are corrected

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	July 19, 2017
Quarrying Permit No.		Inspection Date:	August 10, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 14.2 James Creek		
Current Stage of Operation:	on going		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	U				
Chemicals	U				
Wastes	U				
Fuel Storage	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				
Time as Permitted	A				

Explanatory Remarks -

James Creek Km 14.2:

During the inspection it was observed that the camp area and fuel storage were both satisfactory at the time of the inspection.

Previous inspection reports dated July 14 and July 20, 2017 indicated the presence of garbage debris and unused loose metals.

Today's inspection still shows that debris is still scattered through out the property. The presence of batteries are a concern and we remind you of condition 26(1)(g) Use, Storage, Handling, and Ultimate Disposal of Any Chemical or Toxic Material - Item 9. states:

"The Permittee shall dispose of all toxic substances by removal to an approved facility."

Please ensure that the terms and conditions of your permit are followed and known to all personal on site.



ENVIRONMENTAL INSPECTION REPORT

If there is a requirement to temporarily store debris/metals until removal to a authorized land fill, please locate all debris/metals in one area in an orderly fashion.

MATTERS FOR FOLLOW UP

Ensure observations made are corrected.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2
Battery





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Battery



Figure 4
unused loose metals





ENVIRONMENTAL INSPECTION REPORT

Figure 5
west entrance area



Figure 6
unused loose metals





ENVIRONMENTAL INSPECTION REPORT

Figure 7
debris on side of road



Figure 8
unused loose metals

