



Telephone: 867-777-8907  
Fax: 867-777-2090

February 21, 2019

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

Attention: **Mohammad Hossain**

File Number **G13H004**  
Type of Operation **FUEL CACHES**  
Location **James Creek**

Dear Mohammad Hossain,

An inspection of the above noted operation was conducted on February 20, 2019 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:  
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region  
GLWB

Bag Service 1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 11, 2020
<b>Land Use Permit No.</b>	G13H004	<b>Previous Inspection:</b>	January 17, 2019
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	February 20, 2019
<b>Contractor:</b>	DOI	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek		
<b>Current Stage of Operation:</b>	on-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	James Creek			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	U			
Fuel Storage	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

James Creek:

During the inspection on February 20, 2019 at the James Creek Maintenance camp there was only 1 concern observed by the inspectors.

There was a large oil storage container that is full and stored near the road which does not have a secondary containment. This container of oil should be removed as soon as possible to prevent spills.

The site was clean and in good order, there is a lot less equipment at the site from the last inspection.

Representative Signature

Inspector's Signature

<b>Date:</b>	February 20, 2019	<b>Permit #:</b>	G13H004	<b>Page No:</b>	1
--------------	-------------------	------------------	---------	-----------------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2



Date:	February 20, 2019	Permit #:	G13H004	Page No:	2
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	February 20, 2019	Permit #:	G13H004	Page No:	3
-------	-------------------	-----------	---------	----------	---