



Telephone: 867-777-8907  
Fax: 867-777-2090

January 9, 2019

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

**Attention: Mohammad Hossain**

**File Number** G13H004  
**Type of Operation** FUEL CACHES  
**Location** Km 14.2 James Creek

Dear Mohammad Hossain,

An inspection of the above noted operation was conducted on January 08, 2019 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

**ORIGINAL SIGNED**

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region  
AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board  
Merle Carpenter, Regional Superintendent, Department of Infrastructure, Beaufort Delta Region



## ENVIRONMENTAL INSPECTION REPORT

### FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF December 05, 2018

Confirm that the spills at the coordinates provided in the September 17, 2018 report are cleaned up. The coordinates are as follows:

N 67° 08' 31.1" W 135° 59' 48.3" N 67° 08' 31.5" W 136° 00' 00.5"

The two unacceptable conditions for Facilities and Chemicals will remain until it has been verified that the hydrocarbon spills have been properly cleaned up and disposed of.

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 11, 2020
<b>Land Use Permit No.</b>	G13H004	<b>Previous Inspection:</b>	December 05, 2018
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	January 08, 2019
<b>Contractor:</b>	DOI	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 14.2 James Creek		
<b>Current Stage of Operation:</b>	On-going		
<b>Program Modifications Approved:</b>			

### Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	U				
Erosion (Control or Prevention)	A				
Chemicals	U				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**

James Creek:

During the inspection on January 8, 2019 at the James Creek maintenance camp there were no concerns at the time of the inspection.

The site was clean and organized and there is less equipment at the site then in the past.

The unacceptables are explained in the section, matters for followup of this report.



# ENVIRONMENTAL INSPECTION REPORT

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature

Date:	January 08, 2019	Permit #:	G13H004	Page No:	2
-------	------------------	-----------	---------	----------	---



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**This fuel pump is now in use**



**Figure 2**

**Fuel spill kit and spill tray**







# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

