



Telephone: 867 777-8900

Fax: 867-777-2090

October 7, 2016

RECEIVED
OCT 19 2016

GNWT Department of Transportation
P.O. Box 2038
Inuvik, NT X0E 0T0

Attention: Arvind Vashishtha

File Number G13H004
Type of Operation FUEL CACHES
Location James Creek

To: Arvind Vashishtha,

An inspection of the above noted operation was conducted on October 06, 2016 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Conrad Baetz, Superintendent Dept of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Transportation	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	September 28, 2016
Quarrying Permit No.		Inspection Date:	October 06, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	James Creek		
Current Stage of Operation:	ongoing		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Location as Permitted	A				
Equipment as Approved (Type & Size)	A				
Wastes	A				
Facilities	A				
Chemicals	A				
Fuel Storage	A				

Explanatory Remarks -

James Creek Km 14.2:

All matters with regards to previous inspection report dated Sept 01 2016 was being done and corrected. The heavier material such as the waste metal and old fuel storage tanks will be removed at a later date.

Please advise the Dept. of Lands as to when this will be done or is being removed.

With regards to the fuel spill clean up nothing evident for change from previous inspection as no crew was on site.

It is understood that the waste material from the Fuel spill clean up will be stored on site until the proper permits are issued for a waste disposal site are completed.

Please provide the Department with a final detailed report on the clean up. This report is to ensure that all parties involved are made aware what has been done to date and the GNWT DOT's next step on this matter.



ENVIRONMENTAL INSPECTION REPORT

MATTERS FOR FOLLOW UP

Ensure material is removed from site and report on spill recieved

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:


Figure 1

Old Fuel tanks



Figure 2

Old Fuel tanks





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Waste oil to be removed



Figure 4
used batteries to be removed





ENVIRONMENTAL INSPECTION REPORT

Figure 5
waste metal to be removed



Figure 6
waste metal to be removed





ENVIRONMENTAL INSPECTION REPORT

Figure 7
view of stripped area from spill



Figure 8
View of land farm





ENVIRONMENTAL INSPECTION REPORT

Figure 9
view of land farm

