



Telephone: 867 777-8900

Fax: 867-777-2090

July 20, 2017

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Arvind Vashishtha

File Number G13H004
Type of Operation FUEL CACHES
Location Km 14.2 James Creek

To: Arvind Vashishtha,

An inspection of the above noted operation was conducted on July 19, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

It should be noted that the permit is under the GNWT DOT(now DOI) and the permittee is to abide by the set of conditions on that permit. It is the permit holders responsibility to ensure that these Terms and Conditions are followed irregardless of who maybe at the site

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Dept of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF July 12, 2017

Ensure observations are dealt with and Terms and Conditions of the L.U.P. are met.

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	July 12, 2017
Quarrying Permit No.		Inspection Date:	July 19, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 14.2 James Creek		
Current Stage of Operation:	on going		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	James Creek Km 14.2			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Chemicals	A			
Wastes	U			
Fuel Storage	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -

James Creek Km 14.2:

No environmental concerns was observed to the camp and fuel storage area, the nozzle was locked in and learned that this dispenser is not working, further observed that fuel is taken at the back of the storage tank and nozzle was properly stored and locked. However it was observed that on the previous inspection dated July 14, 2017 at the entrance area the items indicated as the single battery, garbage on the side of the road loose metals are still at same location and not taken care of.

MATTERS FOR FOLLOW UP

Ensure items identified are corrected

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature

Date:	July 19, 2017	Permit #:	G13H004	Page No:	1
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1
nozzle and dispenser at front



Figure 2
at back of storage tank





ENVIRONMENTAL INSPECTION REPORT

Figure 3
land farm



Figure 4
At the southerly entrance to site by hill.





ENVIRONMENTAL INSPECTION REPORT

Figure 5

At the southerly entrance to site.



Figure 6





ENVIRONMENTAL INSPECTION REPORT

Figure 7



Date:	July 19, 2017	Permit #:	G13H004	Page No:	5
-------	---------------	-----------	---------	----------	---