



Telephone: 867-777-8907

Fax: 867-777-2090

July 18, 2018

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number: G13H004  
Type of Operation: FUEL CACHES  
Location: James Creek

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on July 17, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 11, 2018
<b>Land Use Permit No.</b>	G13H004	<b>Previous Inspection:</b>	July 10, 2018
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	July 17, 2018
<b>Contractor:</b>	DOI	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek		
<b>Current Stage of Operation:</b>	on-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>James Creek</b>				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	U				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks - James Creek:**

During the inspection on July 17, 2018 at the James Creek maintenance camp there were a couple of concerns observed by the inspectors.

There was a small pile of gravel with rags in it that was saturated with oil on the south entrance that should be cleaned up immediately. It is small things like this that add up and grow to be a bigger concern if not addressed in a timely manner. The gravel conveyer is still at the site and in the last inspection there was a recommendation it be removed as it is not in the equipment list for the site permit.

Department of Lands has seen a big improvement at the camp in the last month but it is small oil spills that are not cleaned up that causes concerns.

Department of Lands is there to ensure that the environment is protected for future generations and we hope to work with the contractors to keep it that way.

Representative Signature

Inspector's Signature

Date:	July 17, 2018	Permit #:	G13H004	Page No:	1
-------	---------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**



Date:	July 17, 2018	Permit #:	G13H004	Page No:	2
-------	---------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	July 17, 2018	Permit #:	G13H004	Page No:	3
-------	---------------	-----------	---------	----------	---