



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	February 17, 2017
Quarrying Permit No.		Inspection Date:	April 26, 2017
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	James Creek		
Current Stage of Operation:	Ongoing		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Location as Permitted	A				
Equipment as Approved (Type & Size)	A				
Wastes	A				
Facilities	A				
Chemicals	A				
Fuel Storage	U				

Explanatory Remarks -

James Creek Km 14.2:

During the inspection on April 26, 2017 it was observed that the fuel nozzle on the fueling station is not in any secondary containment although the nozzle is locked with a chain and padlock it may not be in use. It was mentioned in numerous reports that a secondary containment must be located at the fueling station and it is also stated in the terms and conditions of the permit.

There are 2 damaged semi trucks parked at the back of the site near the treatment cells but there was no evidence of spills under them, the rest of the site was in good condition.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

2 semi trucks at the back of the site



Figure 2

1 of the trucks at the back of the site





ENVIRONMENTAL INSPECTION REPORT

Figure 3
the other truck at the back of the site



Figure 4
Fueling station





Telephone: 867-777-8907

Fax: 867-777-2090

April 27, 2017

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Arvind Vashishtha

File Number: G13H004
Type of Operation: FUEL CACHES
Location: James Creek

Dear Arvind Vashishtha,

An inspection of the above noted operation was conducted on April 26, 2017 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Acting Superintendent, Department of Lands, Beaufort Delta Region

GLWB