



Telephone: 867 777-8900  
Fax: 867-777-2090

February 11, 2019

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

**Attention: Mohammad Hossain**

<b>File Number</b>	<b>G14E002</b>
<b>Type of Operation</b>	<b>QUARRY SITE - Existing</b>
<b>Location</b>	<b>Km 235</b>

To: Mohammad Hossain,

An inspection of the above noted operation was conducted on February 11, 2019 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

**ORIGINAL SIGNED**

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region  
GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	September 21, 2019
<b>Land Use Permit No.</b>	G14E002	<b>Previous Inspection:</b>	January 23, 2019
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	February 11, 2019
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 235		
<b>Current Stage of Operation:</b>	blasting and crushing complete		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 235				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**

**Km 235:**

During the inspection it was observed that work was completed at site and equipment was removed. The stockpile is located at the north east side of the pit, please note that all aspects was satisfactory with the Land Use Permit. Quarry permit condition # 8 for Pre data has been provided, it is understood that the post data as per condition # 9 will be provided at a later date as communicated by the surveyor. Please note that you are required by condition # 12 to provided a monthly quarry return by the tenth of each month as well this to inform that your quarry permit 2017QP0015 will expire on June 06 2019.



## ENVIRONMENTAL INSPECTION REPORT

### **MATTERS FOR FOLLOW UP**

Post data to be provided as well a monthly quarry return.

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature

Date:	February 11, 2019	Permit #:	G14E002	Page No:	2
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

