



Telephone: 867 777-8900

Fax: 867-777-2090

July 14, 2017

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

Attention: Arvind Vashishtha

received  
19.7.17

File Number G14E002  
Type of Operation QUARRY SITE - Existing  
Location Dempster Highway

To: Arvind Vashishtha,

An inspection of the above noted operation was conducted on July 12, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Dept of Lands, Beaufort Delta Region  
GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	May 24, 2019
<b>Land Use Permit No.</b>	G14E002	<b>Previous Inspection:</b>	September 28, 2015
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	July 12, 2017
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Dempster Highway		
<b>Current Stage of Operation:</b>	ongoing		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Dempster Highway			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Wildlife and Fisheries Habitat (Protection)	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

**Dempster Highway:**

During this inspection it was observed at Km 06 material was stored at this location on another government project, all was satisfactory at this location. Km 27 the GeoTech work is ongoing with no environmental concerns. Bruce Krutko informed that work may/will be done at around Km 32 for the road and material will be required from Km 28.8 which currently is for 800cm and that this will not be enough for the work there. Bruce was advised that a request for an amendment can be made for the required amount. Otherwise no environmental concerns observed with this LUP at the time of the inspection.

N/A

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature

Date:	July 12, 2017	Permit #:	G14E002	Page No:	1
-------	---------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**  
**Km 06**



**Figure 2**  
**Km 06**







# ENVIRONMENTAL INSPECTION REPORT

Figure 3

Km 06



Figure 4

Km 27







# ENVIRONMENTAL INSPECTION REPORT

Figure 5

Km 27



Figure 6

Km 27







# ENVIRONMENTAL INSPECTION REPORT

Figure 7  
Km 28.8



Figure 8  
Km 28.8



Date:	July 12, 2017	Permit #:	G14E002	Page No:	5
-------	---------------	-----------	---------	----------	---