



Telephone: 867 777-8900
Fax: 867-777-2090

March 5, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number G14E002
Type of Operation QUARRY SITE - Existing
Location Km 235

To: Jahangir Hossain,

An inspection of the above noted operation was conducted on March 05, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF February 20, 2018

Ensure Pre data is provided as per item 8 of the quarry permit.

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	February 20, 2018
Quarrying Permit No.		Inspection Date:	March 05, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 235		
Current Stage of Operation:	Crushing and stock piling in progress		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 235				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	U				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Km 235:

It was observed that crushing and stock piling is now in progress, the crushed material is being stock piled at the east side of the pit floor. Clean up to the blasted area was also being done.

Please note that it was requested on previous inspections dated Jan. 18, 2018, Jan. 30, 2018 and February 20, 2018 that the pre surveyed data be provided this is to inform that this data has not been received.

The unsatisfactory given here is for the following;

Inspector would like to bring to your attention that not only are the Terms and Conditions of your Land Use Permit are to be complied with, but also the Terms and Conditions of your quarry permit of which item number 8 states "Pre-surveys must be submitted to the land use inspector, 10 days prior



ENVIRONMENTAL INSPECTION REPORT

to the commencement of operations, for approval."

This again is a repetitive request and it should be noted that it is the Proponents responsibility to ensure that these conditions are adhered to.

MATTERS FOR FOLLOW UP

Ensure pre data is provided as per terms and conditions

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	March 05, 2018	Permit #:	G14E002	Page No:	4
-------	----------------	-----------	---------	----------	---