



Telephone: 867 777-8900

Fax: 867-777-2090

March 29, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number	G14E002
Type of Operation	QUARRY SITE - Existing
Location	Km 235 and Km 178

To: Jahangir Hossain,

An inspection of the above noted operation was conducted on March 28, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF March 21, 2018

Ensure Pre and Post data is provided.

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	March 21, 2018
Quarrying Permit No.		Inspection Date:	March 28, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 235 and Km 178		
Current Stage of Operation:	Km 235 complete Km 178 stock piling in progress		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 235	Km 178		
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wastes	A			
Restoration of Lands	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
Location as Permitted	A			
Time as Permitted	U			
Equipment as Approved (Type & Size)	A			
Location as Permitted		A		
Time as Permitted		A		
Equipment as Approved (Type & Size)		A		
Facilities		A		
Wildlife and Fisheries Habitat (Protection)		A		
Permits		A		
Matters not Inconsistent		A		
Sections 8 to 12 / 14 to 16 M.V.L.U.R.		A		
Explanatory Remarks - Km 178: During this inspection it was observed that previous inspection requests dated March 22, 2018 was being done as requested.				



ENVIRONMENTAL INSPECTION REPORT

All environmental concerns was satisfactory at time of the inspection.

Km 235:

During the inspection it was observed that all work is completed and no further activity has taken place since previous inspection conducted on March 21 2018. It was requested that the Pre and Post data was to be provided please note that as of this inspection date no data has been received.

MATTERS FOR FOLLOW UP

Proponent to provide Pre and Post data for Km 235 as requested.

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Km 178 Rengling River



Figure 2

Km 178 Rengling River



Date:	March 28, 2018	Permit #:	G14E002	Page No:	3
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3
Km 235



Figure 4
Km 235

