



Telephone: 867 777-8900
Fax: 867-777-2090

March 6, 2018

Arctic Tire (1980) Ltd
P.O. Box 3190
Inuvik, NT X0E 0T0

Attention: Brian McCarthy

File Number G14Q003
Type of Operation QUARRY SITE - Existing
Location Km 251

To: Brian McCarthy,

An inspection of the above noted operation was conducted on March 05, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF February 20, 2018

Permittee:	Arctic Tire (1980) Ltd	Permit Expiry Date:	June 22, 2019
Land Use Permit No.	G14Q003	Previous Inspection:	February 20, 2018
Quarrying Permit No.		Inspection Date:	March 05, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	completed		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Permits	U			
Restoration of Lands	A			
Location as Permitted	A			
Time as Permitted	A			

Explanatory Remarks -

Km 251:

During this inspection it was observed that the material was removed from site, however no returns or contacting inspector to inform of such removal.

Please note that as per conditions of your permit under Part A Scope of Permit item number 3 states;

"Compliance with the terms and conditions of this Permit does not excuse the Permittee from its obligation to comply with the requirements of any applicable Federal, Territorial, or municipal legislation."

Also under your Quarry Permit condition item 15 which states:

"This permit is subject to the provisions of the Territorial Quarry Regulations and the conditions set out herein. Failure to comply with the provisions of the Regulations and the conditions prescribed in this permit may result in cancellation of the permit in accordance with Section 9(6) of the Territorial Quarrying Regulations without prior notice to the Permittee."

Please ensure that data is provided to inspectors in regards to when the material was removed and the full amount removed as the last quarry return for February 2018 indicated an amount of 200 cm removed from site.



ENVIRONMENTAL INSPECTION REPORT

MATTERS FOR FOLLOW UP

Permittee to provide full amounts removed from site.

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2

