



Telephone: 867 777-8900

Fax: 867-777-2090

March 29, 2018

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number	G16Q004
Type of Operation	QUARRY SITE - Existing
Location	Km 251

To; Lyle Gully,

An inspection of the above noted operation was conducted on March 28, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region

GLWB



### ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF March 21, 2018

Permittee to provide pre and post data for quarry permit 2016QP0016 and material is being removed from site..

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	March 21, 2018
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	March 28, 2018
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>	completed		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	U			
Restoration of Lands	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

Km 251:

No changes since previous inspection dated March 22, 2018. Please note that this is the third request to provide Pre and Post data for quarry permit number 2016QP0016. Please ensure that this data is provided as requested.

**MATTERS FOR FOLLOW UP**

Permittee to provide pre and post data for quarry permit 2016QP0016 as well remove material and equipment from site.

*N/A*

Representative Signature

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
Figure 1



Figure 2





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	March 28, 2018	Permit #:	G16Q004	Page No:	3
-------	----------------	-----------	---------	----------	---