



Telephone: 867 777-8900

Fax: 867-777-2090

January 2, 2018

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number	G16Q004
Type of Operation	QUARRY SITE - Existing
Location	Km 251

To: Lyle Gully,

An inspection of the above noted operation was conducted on January 02, 2018 by Manager, Resource Management Donald Arey and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

Please ensure that the Pre and Post data are provided to the Department of Lands A.S.A.P.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	December 19, 2017
Quarrying Permit No.		Inspection Date:	January 02, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	Ongoing		
Program Modifications Approved:	New QP issued		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	Km 251
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A
Location as Permitted	A
Time as Permitted	U
Equipment as Approved (Type & Size)	A
Methods & Techniques	A
Facilities	A
Chemicals	A
Wastes	A
Historical / Archaeological Sites	A
Ecological Resources	A
Fuel Storage	A
Restoration of Lands	A
Matters not Inconsistent	A

Explanatory Remarks -

Km 251: During the inspection it was observed that work was completed at the site. The quarry application was for the amount of 5000 cm. The unsatisfactory given is for not notifying inspectors that work has/will commence. The work location was previously discussed in Oct. 2017 and work done on location was satisfactory to inspector, no other environmental concerns was observed.

Please ensure that the Pre and Post surveyed data are provided to the Dept. of Lands as soon as possible.

Also please note that all stock piled material is to be removed from site.

MATTERS FOR FOLLOW UP

ensure that the Pre and Post data are provided to the Department of Lands A.S.A.P.

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

