



Telephone: 867 777-8900

Fax: 867-777-2090

July 12, 2017

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: **Lyle Gully**

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location KM 251 Quarry

To Lyle Gully,

An inspection of the above noted operation was conducted on July 11, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF June 26, 2017

Monitor removal of stock piles

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	June 26, 2017
Quarrying Permit No.		Inspection Date:	July 11, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	KM 251 Quarry		
Current Stage of Operation:	Ongoing		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Time as Permitted	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
Facilities	A			
Chemicals	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Fuel Storage	A			
Permits	A			
Matters not Inconsistent	A			
Location as Permitted	A			

Explanatory Remarks -

During the inspection it was observed that the stock piles which were requested to be removed in the previous inspection report dated June 27, 2017 have not yet been removed. At this time the Department of Lands is again requesting you to remove the stockpiles of crushed material from the pit.

Also, there is equipment in the pit that is not currently being utilized. The Department of Lands is also requesting you to remove any unnecessary equipment.

Due to the fact that this is a multi-user pit, it is necessary to keep the areas clean and clear of obstructions, which can be hazardous to yourself and other users.

MATTERS FOR FOLLOW UP

Remove unnecessary equipment and stockpiles of material.

N/A

Representative Signature

Inspector's Signature

Date:	July 11, 2017	Permit #:	G16Q004	Page No:	1
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

A picture of the entire pit with the equipment and stockpiles. The removal of the loading ramp is an indication that there will be no further crushing of the material.



Figure 2

Another picture of the same crusher pointed out in the previous picture.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

A picture of another crusher with some more stockpiles.



Date:	July 11, 2017	Permit #:	G16Q004	Page No:	3
-------	---------------	-----------	---------	----------	---