



Telephone: 867-777-8907

Fax: 867-777-2090

May 1, 2018

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

Dear Lyle Gully,

An inspection of the above noted operation was conducted on April 30, 2018 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF March 28, 2018

Permittee to provide pre and post data for quarry permit 2014QP0023 as well remove material and equipment from site.

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	March 28, 2018
Quarrying Permit No.		Inspection Date:	April 30, 2018
Contractor:	Bob's Welding LTD	Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	Removing material from the pit floor		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	U			
Restoration of Lands	A			
Matters not Inconsistent	U			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -

Km 251:

During the inspection on April 30, 2018 at km 251 there was not much change from the last inspection dated March 28, 2018. There is a crew loading and hauling material from a stock pile on the south mid section of the pit.

Please note that this is the fourth request for the pre and post data for the file 2014QP0023, Department of Lands did receive PDF copies but no electronic data was provided.

Please continue to remove the quarried material and equipment from the site as requested in previous inspection reports.

Representative Signature

Inspector's Signature

Date:	April 30, 2018	Permit #:	G16Q004	Page No:	1
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

