



Telephone: 867-777-8907

Fax: 867-777-2090

January 24, 2018

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number                    G17Q007  
Type of Operation            QUARRY SITE - Existing  
Location                        Km 66

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on January 17, 2018 by Resource Management Officer II Herbert Allen.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	
<b>Land Use Permit No.</b>	G17Q007	<b>Previous Inspection:</b>	New
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	January 17, 2018
<b>Contractor:</b>	DOI	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 66		
<b>Current Stage of Operation:</b>	No work being conducted at this time		
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>Km 66</b>				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**

**Km 66:**

During the inspection on January 17, 2018 no work was being conducted at the site at this time. The site looked clean of debris from the last fall inspection. There are 3 end dumps and a semi truck parked off to the side on the north end at the site.

*NA*

\_\_\_\_\_  
Representative Signature

*[Handwritten Signature]*

\_\_\_\_\_  
Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

