



Telephone: 867-777-8907
Fax: 867-777-2090

July 4, 2019

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Merle Carpenter

File Number G17X006
Type of Operation MISC.
Location Km 15

Dear Merle Carpenter,

An inspection of the above noted operation was conducted on June 27, 2019 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Donald Arey, Acting Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF January 23, 2019

January 23, 2019

Follow up with the request for an update with future plans for the site.

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 02, 2023
Land Use Permit No.	G17X006	Previous Inspection:	January 23, 2019
Quarrying Permit No.		Inspection Date:	June 27, 2019
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 15		
Current Stage of Operation:	waiting for closer		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 15			
Location as Permitted	A			
Time as Permitted	A			
Methods & Techniques	A			
Erosion (Control or Prevention)	U			
Wildlife and Fisheries Habitat (Protection)	U			

Explanatory Remarks -

Km 15:

During the inspection on June 27, 2019 the inspectors noticed there were some rutting in the area where the thermistors were removed from. The rutting is deep enough to hold water and will be a concern when it rains and could cause erosion.

There is also 2 thermistor piping that are visible after they were cut above the ground level and should have been cut below ground level.

This permit will remain open until Department of Lands is satisfied that no environmental effects will occur due to the impacts on the land.

26(1)(o) Restoration of the Lands

Prior to the expiry date of this permit, the permittee shall complete all cleanup and restoration of the land used.

Representative Signature

Inspector's Signature

Date:	June 27, 2019	Permit #:	G17X006	Page No:	1
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5




Figure 6

