



Telephone: 867-777-8907

Fax: 867-777-2090

October 25, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Mohammad Hossain

File Number	G18Q003
Type of Operation	QUARRY SITE - Existing
Location	Frog Creek

Dear Mohammad Hossain,

An inspection of the above noted operation was conducted on October 24, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

ORIGINAL SIGNED

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
Alec Sandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board
Stephen Charlie, Director of Lands and Resources, Gwich'in Tribal Council



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	July 23, 2023
Land Use Permit No.	G18Q003	Previous Inspection:	October 17, 2018
Quarrying Permit No.		Inspection Date:	October 24, 2018
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	Frog Creek		
Current Stage of Operation:	on-going		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 126				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Location as Permitted	A				
Time as Permitted	A				

Explanatory Remarks -

Km 126:

During the inspection on October 24, 2018 there were no concerns observed by the inspectors.

The stock pile of crushed material was removed from the site and hauled to different locations along the Dempster Highway.

There was no crushing of material occurring at the site during the inspection. The contractor was working on removing the stock pile of uncrushed material from the south section of the pit by the crushers..

Representative Signature

Inspector's Signature

Date:	October 24, 2018	Permit #:	G18Q003	Page No:	1
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Area where to crushed material was stored at Frog Creek site.



Figure 2

Area where to crushed material was stored at Frog Creek site.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

South side of the pit where the uncrushed material was be removed.



Figure 4

South side of the pit where the uncrushed material was be removed.

