



Telephone: 867-777-8907
Fax: 867-777-2090

July 4, 2019

GNWT Department of Infrastructure
Bag Service 1
Inuvik, NT X0E 0T0

Attention: Merle Carpenter

File Number: G19S003
Type of Operation: SOIL TESTING (GEOTECH)
Location: Km 28.7

Dear Merle Carpenter,

An inspection of the above noted operation was conducted on June 27, 2019 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC: ✓
Donald Arey, Acting Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	March 19, 2024
Land Use Permit No.	G19S003	Previous Inspection:	June 18, 2019
Quarrying Permit No.		Inspection Date:	June 27, 2019
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 28.7		
Current Stage of Operation:	There no work being conducted at this time.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 28.8				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Km 28.8:

During the inspection on June 27, 2019 there was no work being conducted at Km 28.7 at this time.

Please contact Department of Lands Inspectors 48 hours prior to any work that is to be conducted at the site as indicated in the terms and conditions of this land use permit.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	June 27, 2019	Permit #:	G19S003	Page No:	3
-------	---------------	-----------	---------	----------	---