



Aboriginal Affairs and
Northern Development Canada

Affaires autochtones et
Développement du Nord Canada

<http://www.aandc-aadnc.gc.ca>

<http://www.aadnc-aandc.gc.ca>

South Mackenzie District
41 Capital Drive #203
Hay River, NT X0E 1G2

Telephone: 867 874-6994
Fax: 867 874-2460

September 10, 2013

Deninu K'ue Development Corp.
PO Box 1899
Fort Resolution, NT X0E 0M0

Attn: Stephen Cuthbert, General Manager

**RE: Land Use Permit MV2004W0041
LOGGING OPERATION
NWT Highway No. 6 near Km 74.**

Dear Mr. Cuthbert,

An inspection of the above noted operation was conducted on July 11, 2013 by Resource Management Officer Norm McCowan and Field Operations Supervisor Rob Walker.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

Land Use Permit MV2002W0041 expired on December 15, 2009 and all clean-up and restoration of the lands used was required to have been completed by the expiry date. It is noted in this inspection report that the removal of the mill equipment and restoration of the lands has not yet been completed. **You are hereby directed to have the clean-up and restoration of the mill site completed by September 30, 2014.**

If you have any questions or concerns, I can be reached at (867) 874-6994 ext 24.

Sincerely,

Original Signed

Norm McCowan
Resource Management Officer

cc: District Manager, South Mackenzie District, AANDC
Mackenzie Valley Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Deninu K'ue Development Corp.	Permit Expiry Date:	December 15, 2009
Land Use Permit No.	MV2004W0041	Previous Inspection:	June 27, 2012
Quarrying Permit No.	N/A	Inspection Date:	July 11, 2013
Contractor:		Subcontractor:	
Location(s) Inspected:	Millsite on the east side of NWT Highway No. 6 near Km 74.		
Current Stage of Operation:	No logging operations since April 2006. Land use permit expired on December 15, 2009.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Mill				
Location as Permitted	N/A				
Time as Permitted	N/A				
Equipment as Approved (Type & Size)	N/A				
Methods & Techniques	N/A				
Facilities	N/A				
Erosion (Control or Prevention)	N/A				
Chemicals	N/A				
Wildlife and Fisheries Habitat (Protection)	N/A				
Wastes	U (41)				
Historical / Archaeological Sites	N/A				
Fuel Storage	N/A				
Brush Disposal	N/A				
Restoration of Lands	U (61)				
Permits	N/A				

Explanatory Remarks -

Mill Site:

Land Use Permit MV2004W0041 expired on December 15, 2009. In accordance with Permit Condition #61 (CLEAN-UP), the Permittee was to have completed all clean-up and restoration of the lands used prior to the expiry date of this land use permit.

This land use permit has not been active for logging since April of 2006. The clean-up and removal of all mill equipment, 10' x 30' metal trailer, 2 fuel tanks, waste metal, garbage and debris at the main mill site remains outstanding (Permit Conditions 41 & 61).

Fuel contaminated soil was observed around the mill equipment. It is required that all contaminated soil be cleaned up and hauled to an authorized disposal site. This work must be completed after the mill has been hauled away to ensure all hydrocarbon impacted soils are removed from site.

It is required that all clean-up and restoration of the mill site be completed by September 30, 2014. The permit area must be restored to substantially the same condition as it was prior to the commencement of the operation.

Original Signed

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Mill Site near Km 75, NWT Highway No. 6 must be removed from the land use area



Figure 2

Mill Site near Km 75, NWT Highway No. 6 must be removed from the land use area





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Fuel contaminated soil near the mill must be cleaned-up



Figure 4

Metal trailer and discarded machinery parts must be removed from land use area





ENVIRONMENTAL INSPECTION REPORT

Figure 5

Waste lumber requires total disposal



Figure 6

Brush disposal is required

