





2010 – 2012 Water Quality Results for SNP Station 43-1
Treated Minewater Discharged from the Giant Mine Polishing Pond to Baker Creek




Total Copper Concentrations at SNP 43-1 (2010 to 2012)




Cyanide Concentrations at SNP 43-1 (2010 to 2012)




Total Lead Concentrations at SNP 43-1 (2010 to 2012)




Total Nickel Concentrations at SNP 43-1 (2010 to 2012)





Oil & Gas Concentrations at SNP 43-1 (2010 to 2012)




Total Suspended Solids (TSS) at SNP 43-1 (2010 to 2012)






Dissolved Arsenic Concentrations at SNP 43-1 (2010 to 2012)



Radium-226 Concentrations at SNP 43-1 (2010 to 2012)



Discharge to Baker Creek at SNP 43-1 (2010 to 2012)

