



Telephone: 867 874-6994
Fax: 867 874-2460

October 14, 2020

ProCore Drilling Ltd.
28067B Mackenzie Highway
email: ddean@northwestel.net
Hay River, NT X0E 0R4

Attention: Darrel Dean

File Number	MV2013Q0017
Type of Operation	QUARRY SITE - New
Location	Km 34.1, Sites A & C, NWT Highway No. 5

Dear Mr. Dean,

An inspection of the above noted operation was conducted on August 18, 2020 by Resource Management Officer Jayda Robillard and Manager, Resource Management Rob Walker.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: MVLWB
Charlene Coe, Land Use Advisor – North Slave
Derise Rehm, Regional Superintendent South Slave



ENVIRONMENTAL INSPECTION REPORT

Permittee:	ProCore Drilling Ltd.	Permit Expiry Date:	May 21, 2021
Land Use Permit No.	MV2013Q0017	Previous Inspection:	May 22, 2019
Quarrying Permit No.	20/0031	Inspection Date:	August 18, 2020
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 34.1, Sites A & C, NWT Highway No. 5		
Current Stage of Operation:	Permittee has done some quarrying at Site C this season under the authority of quarry permit #2017QP0025.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Site A	Site C			
Location as Permitted	A	A			
Time as Permitted	A	A			
Equipment as Approved (Type & Size)	A	A			
Methods & Techniques	A	A			
Facilities	A	A			
Erosion (Control or Prevention)	A	A			
Chemicals	A	A			
Wildlife and Fisheries Habitat (Protection)	A	A			
Wastes	A	A			
Historical / Archaeological Sites	N/A	N/A			
Fuel Storage	A	U			
Brush Disposal	N/A	N/A			
Restoration of Lands	N/A	N/A			
Permits	A	A			
Matters not Inconsistent	A	A			

Explanatory Remarks -

Site C:

Permittee has an excavator parked near the west end of Site C. Granular material has been removed from Site C this season under the authority of quarry permit #2017QP0025, which was expired on August 31, 2020. A new permit #2020QP0031 was issued in September, 2020.

During the inspection it was noted that there was no drip tray beneath the excavator. **Condition 35** of your land use permit requires *"All equipment that may be parked for two hours or more, should have a haz-mat/drip tray under it or be sufficiently diapered."* Please ensure drip trays are being used under equipment or remove the equipment from the territorial lands.



ENVIRONMENTAL INSPECTION REPORT

Note your land use permit expires on May 21, 2021. No further extensions can be granted to the permit. Please contact the Mackenzie Valley Land and Water Board to apply for a new permit prior to the expiry to avoid any interruption in your operation.

Site A:

No sign of recent activity. Site continues to be used as a shooting range by parties unknown.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Site C: Stockpile



Figure 2

Site C: Quarrying has taken place at the west end of Site C.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Site C: Excavator is parked without a drip tray.



Figure 4

Site C: Quarrying has taken place at the west end of Site C.





ENVIRONMENTAL INSPECTION REPORT

Figure 5

Site A: Stockpile near the entrance of Site A.



Figure 6

Site A: Large stockpile at Site A.





ENVIRONMENTAL INSPECTION REPORT

Figure 7

Site A: Area is being used as a shooting range by parties unknown.

