



Telephone: 867 874-6994

Fax: 867 874-2460

July 26, 2019

Rowe's Construction
25 Studney Drive
Hay River, NT X0E 0R6

Attention: Jack Rowe

File Number	MV2015Q0022
Type of Operation	QUARRY SITE - Existing
Location	Km 191.6, NWT Highway No. 1

Dear Mr. Rowe,

An inspection of the above noted operation was conducted on July 16, 2019 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. There were no environmental concerns noted during the inspection.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: MVLWB
Charlene Coe, Land Use Advisor North Slave – GNWT Dept of Lands
Derise Rehm-Lepine, Regional Superintendent South Slave – GNWT Dept of Lands



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Rowe's Construction	Permit Expiry Date:	February 17, 2021
Land Use Permit No.	MV2015Q0022	Previous Inspection:	June 26, 2018
Quarrying Permit No.	17/0002	Inspection Date:	July 16, 2019
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 191.6, NWT Highway No. 1		
Current Stage of Operation:	No sign of recent activity.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected


Operating Condition	Aspect Inspected			
	Pit			
Time as Permitted	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Equipment as Approved (Type & Size)	A			
Location as Permitted	A			
Matters not Inconsistent	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Historical / Archaeological Sites	N/A			
Wastes	A			
Methods & Techniques	A			
Fuel Storage	A			

Explanatory Remarks -

There is no sign of activity in the pit this season. A small stockpile of granular material (quarry permit #2014QP0027) remains on site.

No environmental concerns were noted at the time of inspection.

Representative Signature



Inspector's Signature

Date:	July 16, 2019	Permit #:	MV2015Q0022	Page No:	1
-------	---------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

No sign of recent activity.

