



Telephone: 867-872-2558 ext. 24
Fax: 867-872-3472

March 26, 2019

Pine Point Mining Limited
1100 Avenue des Canadiens-de-Montreal
Bureau 300
Montreal, QC H3B 2S2

Attention: Robin Adair, Jeff Hussey

File Number MV2017C0024
Type of Operation MINERAL EXP - drilling
Location W85, Camp, Great Slave staging, Procore staging

Dear Robin Adair, Jeff Hussey,

An inspection of the above noted operation was conducted on March 18, 2019 by Manager, Resource Management Mike Vassal and Manager, Resource Management Rob Walker.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-872-2558 ext. 24.

Sincerely,

Mike Vassal
Manager, Resource Management
Department of Lands
South Slave Region

CC:
Mackenzie Valley Land and Water Board
Land Use Advisor, North Slave Region, Department of Lands
Derise Rehm-Lepine, Superintendent, South Slave Region Department of Lands



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Pine Point Mining Limited	Permit Expiry Date:	July 19, 2022
Land Use Permit No.	MV2017C0024	Previous Inspection:	February 28, 2019
Quarrying Permit No.		Inspection Date:	March 18, 2019
Contractor:		Subcontractor:	
Location(s) Inspected:	W85, Camp, Great Slave staging, Procore staging		
Current Stage of Operation:	There is no current drilling activity and none is planned until the spring. Camp is being operated in maintenance condition. Geophysicists will be working out of the camp from March 27 to April 15, 2019.		
Program Modifications Approved:	NA		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Drill Program				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	N/I				
Matters not Inconsistent	A				

Explanatory Remarks -

Drill Program:

An inspection of the Pine Point Mining (PPM) operation was conducted on March 18, 2019 by Inspectors Mike Vassal and Rob Walker. There was no drilling or exploration taking place. The camp was in maintenance operations with camp attendants on site.

The W85 artesian well was inspected. No H₂S or water flow were observed or detected at W85-18-PP-003. The metal rods are effectively stopping the flow of gas and water (Figure 1



ENVIRONMENTAL INSPECTION REPORT

and 2).

There was no equipment remaining at the Procore staging site (Figure 3), coordinates: 60° 50' 10.0" N 114° 47' 40.9" W. Procore does have a large water tank on the W85 access road and a flatbed trailer at the entrance to W85 at Hwy. 6.

The inspectors met Fred at the camp. The concerns over the sump filling up have been resolved. Fuel is stored with secondary containment and no concerns were noted (Figure 8).

Great Slave Drilling staging area was inspected. There has been no change since the last inspection on February 28, 2019.

As of the date of inspection the roads were in good condition.

Representative Signature



Inspector's Signature

Date:	March 18, 2019	Permit #:	MV2017C0024	Page No:	2
-------	----------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

W85-18-PP-003: Artesian well that was flowing water and H2S has been capped



Figure 2

W85-18-PP-003: Overview of site



Figure 3

Procore staging area: All items have been removed



Figure 4

Camp staging: Drill core boxes



Figure 5

Camp: Sleeping quarters



Figure 6

Camp: Drain pipe and tower





ENVIRONMENTAL INSPECTION REPORT

Figure 7

Camp: Cook and dry tents



Figure 8

Camp: Fuel, tidy tank and generator shed. Secondary containment is used.

