



Telephone: 867-872-2558 ext. 24

Fax: 867-872-3472

August 17, 2017

GNWT - Department of Infrastructure
P.O. Box 1320
Yellowknife, NT X1A 2P9

Attention: Terry Brookes

| | |
|--------------------------|---|
| File Number | MV2017X0018 |
| Type of Operation | HWY MAINTENANCE & OPERATIONS |
| Location | Highway 5, Kilometer 89.1 |

Dear Mr. Brookes,

An inspection of the above noted operation was conducted on June 06, 2017 by Manager, Resource Management Mike Vassal and Resource Management Officer I, Olivia Villebrun.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-872-2558 ext. 24.

Sincerely,

Original Signed

Mike Vassal
Manager, Resource Management
Department of Lands
South Slave Region

CC: Tyree Mullaney, Regulatory Officer, Mackenzie Valley Land and Water Board
Charlene Coe, Land Use Advisor, Department of Lands
Derise Rehm-Lepine, Acting Superintendent, South Slave Region, Department of Lands



ENVIRONMENTAL INSPECTION REPORT

| | | | |
|--|-------------------------------------|-----------------------------|---------------|
| Permittee: | GNWT - Department of Infrastructure | Permit Expiry Date: | May 14, 2022 |
| Land Use Permit No. | MV2017X0018 | Previous Inspection: | June 27, 2012 |
| Quarrying Permit No. | 2015QP0021 | Inspection Date: | June 06, 2017 |
| Contractor: | | Subcontractor: | |
| Location(s) Inspected: | Highway 5, Kilometer 89.1 | | |
| Current Stage of Operation: | Active | | |
| Program Modifications Approved: | N/A | | |

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

| Operating Condition | Aspect Inspected | | | |
|---|------------------|----|--|--|
| | KM 89.1 | | | |
| Location as Permitted | A | | | |
| Time as Permitted | A | | | |
| Equipment as Approved (Type & Size) | A | | | |
| Methods & Techniques | A | | | |
| Facilities | N/A | | | |
| Erosion (Control or Prevention) | A | | | |
| Chemicals | A | | | |
| Wildlife and Fisheries Habitat (Protection) | A | 51 | | |
| Wastes | A | | | |
| Historical / Archaeological Sites | A | | | |
| Fuel Storage | A | | | |
| Brush Disposal | A | | | |
| Restoration of Lands | N/A | | | |
| Permits | N/I | | | |
| Matters not Inconsistent | A | | | |

Explanatory Remarks -

KM 89.1:

Numbers refer to the conditions listed under the Land Use Permit #MV2017X0018.

51: "The Permittee shall take all reasonable measures to prevent damage to wildlife and fish habitat..."

There are swallows nesting in some of the material piles. Please do not use this material until the young have fledged.

There was no one on site during the inspection. A loader and flatbed trailer were on site. No chemical or fuel storage concerns.

Original Signed

Representative Signature

Inspector's Signature

| | | | | | |
|-------|---------------|-----------|-------------|----------|---|
| Date: | June 06, 2017 | Permit #: | MV2017X0018 | Page No: | 1 |
|-------|---------------|-----------|-------------|----------|---|



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

View of quarry



Figure 2

Large material pile



Figure 3

Loader



Figure 4

Example of the bank swallow burrows



Figure 5

Flatbed trailer



Figure 6

View of quarry

