



Telephone: 867-872-2558 ext. 24

Fax: 867-872-3472

August 17, 2017

GNWT - Department of Infrastructure
P.O. Box 1320
Yellowknife, NT X1A 2P9

Attention: Terry Brookes

File Number	MV2017X0018
Type of Operation	HWY MAINTENANCE & OPERATIONS
Location	Km 232, Hwy 5, Salt Mountain.

Dear Mr. Brookes,

An inspection of the above noted operation was conducted on June 13, 2017 by Manager, Resource Management Mike Vassal and Resource Management Officer I Olivia Villebrun.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-872-2558 ext. 24.

Sincerely,

Original signed

Mike Vassal
Manager, Resource Management
Department of Lands
South Slave Region

CC: Tyree Mullaney, Regulatory Specialist, Mackenzie Valley Land and Water Board
Derise Rehm-Lepine, A/Superintendent, South Slave Region
Charlene Coe, Land Use Advisor, Department of Lands



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT - Department of Infrastructure	Permit Expiry Date:	May 14, 2022
Land Use Permit No.	MV2017X0018	Previous Inspection:	August 16, 2016 under MV2010X0011
Quarrying Permit No.	None	Inspection Date:	June 13, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 232, Hwy 5, Salt Mountain.		
Current Stage of Operation:	Active: loader on site		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 232 North side Hwy 5			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	N/I			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A	51		
Wastes	A			
Historical / Archaeological Sites	A			
Fuel Storage	A			
Brush Disposal	U	77		
Restoration of Lands	A			
Permits	N/I			

Explanatory Remarks - Km 232 North side Hwy 5:
 Numbers refer to conditions listed under the Land Use Permit for Permit #MV2017X0018.

51: "The Permittee shall take all reasonable measures to prevent damage to wildlife and fish habitat..."

There are cliff swallows nesting in one of the material piles. Please do not use this material until the young have fledged.

(continued on reverse)



ENVIRONMENTAL INSPECTION REPORT

77. "The Permittee shall progressively dispose of all brush and trees and shall complete all brush disposal..."

When conditions permit the brush should be burned.

Original signed

Representative Signature

Inspector's Signature

Date:	June 13, 2017	Permit #:	MV2017X0018	Page No:	2
-------	---------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Loader and material pile



Figure 2

Material piles



Figure 3

Material piles



Figure 4

Swallow nest sites in material



Figure 5

Wood for disposal when conditions permit

