



Telephone: 867 874-6994

Fax: 867 874-2460

November 10, 2020

Rowe's Construction (851791 NWT Ltd)
25 Studney Drive
Hay River, NT X0E 0R9

Attention: Florian Mandsfeld

File Number MV2018Q0003
Type of Operation QUARRY SITE - New
Location Km 100, NWT Highway No. 1

Dear Mr. Mandsfeld,

An inspection of the above noted operation was conducted on August 07, 2020 by Resource Management Officer Jayda Robillard and Manager, Resource Management Rob Walker.

Enclosed is a copy of the Environmental Inspection Report. No environmental concerns were noted during the inspection.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: MVLWB
Derise Rehm, Regional Superintendent South Slave



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Rowe's Construction (851791 NWT Ltd)	Permit Expiry Date:	March 28, 2023
Land Use Permit No.	MV2018Q0003	Previous Inspection:	October 21, 2019
Quarrying Permit No.	18/0007	Inspection Date:	August 07, 2020
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 100, NWT Highway No. 1		
Current Stage of Operation:	There has been no quarrying activity in the pit this season.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Pit			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			

Explanatory Remarks -

There has been no quarrying activity in the pit this season. No environmental concerns were noted during the inspection.

The existing quarry site has several small stockpiles of processed granular material on site. This material was quarried and processed under the authority of Quarry Permit #2014QP0022.

No environmental concerns were noted during the inspection.

Representative Signature



Inspector's Signature

Date:	August 07, 2020	Permit #:	MV2018Q0003	Page No:	1
-------	-----------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

South side of the clearing.



Figure 2

East side of the quarry. Overburden is windrowed along the edge of the clearing.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Stockpile of processed gravel near the entrance to the pit.

