



Indian and Northern
Affairs Canada
www.inac.gc.ca

Affaires indiennes
et du Nord Canada
www.ainc.gc.ca

Telephone: (867) 587 2912
Fax: (867) 587 2928

Norman Wells Sub-District
P.O. Box 126
Norman Wells, NT X0E 0V0

Our file - Notre référence

April 20, 2004

David Calvert
Coordinator, Surface Land
Aboriginal and Community Relations
Apache Canada Ltd.
1000, 700 9th Ave SW
Calgary, AB
T2P 3V4



S03A-008
S03L1-016
INS. REPORTS

RE: Land Use Permit S03A-008 Nogha/ Tunago

On April 14, an Environmental Inspection was conducted of the above operation. Enclosed is a copy of the Inspection Report. As the exploration activity has been completed for the season, all of the equipment has been removed from the permitted area and the access road has been decommissioned. This Inspector is pleased to report that all of the conditions under this Land Use Permit pertaining to demobilization have been adhered to.

Please note the comments in the Explanatory Remarks section of the Environmental Inspection Report. If you have any questions regarding this or any other matter, please do not hesitate to contact me at (867) 587 2911.

Yours truly,

Danette Sharun

Danette Sharun
Resource Management Officer II
Norman Wells

cc: Inuvik District files
Sahtu Land & Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Apache Canada Ltd. 1000, 700 9 th Ave SW Calgary, AB T2P 3V4		
		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	S03A-008	December 13, 2008	April 06, 2004
Quarrying Permit No.			
Contractor:	Arctic Circle	Subcontractor:	

Location(s) Inspected:	B-23, K-14, access roads and K-14 crew camp location.
------------------------	---

Current Stage of Operation	All equipment has been demobilized from the permitted area. The access road has been decommissioned with stream crossings notched.
----------------------------	--

Program Modifications Approved:	Nil.
---------------------------------	------

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

	Operating Condition	Aspect Inspected			
		B-23	K-14	K-14 camp	Access Road
A	Location as Permitted	A	A	A	A
B	Timing as Permitted	A	A	A	A
C	Equipment as Approved (Type & Size)	A	A	A	A
D	Methods & Techniques	A	A	A	A
E	Facilities	A	A	A	A
F	Erosion (Control or Prevention of Flooding etc.)	A	A	A	A
G	Chemicals	A	A	A	A
H	Wildlife and Fisheries Habitat (Protection)	A	A	A	A
I	Wastes	A	A	A	A
J	Historical / Archaeological / Burial Sites	A	A	A	A
K	Recreational / Scenic Ecological Value	-	-	-	-
M	Fuel Storage	N/A	N/A	N/A	N/A
N	Debris / Brush Disposal	A	A	A	A
O	Restoration of Lands	A	A	A	A
P	Permits	A	A	A	A
-	Matters Not Inconsistent	A	A	A	A
R	Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A	A	A
S					
T					

Explanatory Remarks (attach page 2 if required) No.

The exploration activity under this Land Use Permit has been completed for this season. All equipment and debris has been removed from the permitted area. The access road has been decommissioned and all creek crossings have been notched. The two areas of permafrost identified at wellsite B-23 have been capped and will be monitored for slumping. All sewage and drill waste sumps have been capped and will be monitored over the next 5 years for slumping.

Danette Sharun
Danette Sharun
Resource Management Officer II