



North Mackenzie District  
P.O. Box 126  
Norman Wells, NT, X0E 0V0

Telephone: 867 587-2911  
Fax: 867-587-2928

August 13, 2013

Husky Oil Operations Ltd.  
707-8th Avenue SW  
Calgary, AB T2P 3G7

**Attn: Kim Richardson**

**RE: Land Use Permit S12X-006  
Water Well Drill Sites**

Dear Kim Richardson,

An inspection of the above noted operation was conducted on August 06, 2013 by the undersigned.

Enclosed is a copy of the Environmental Inspection Report. This project created very minimal disturbance. The use of mulchers to clear drill sites resulted in limited brush disposal and worked well in protecting the vegetative mat. All conditions are acceptable but please ensure all wells have the appropriate signage as per condition Q.15.

If you have any questions, please contact me at 867 587-2911.

Sincerely,

Steve Deschene  
Resource Management Officer

Cc: Inuvik District Files  
Sahtu Land and Water Board



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Husky Oil Operations Ltd.	<b>Permit Expiry Date:</b>	December 04, 2017
<b>Land Use Permit No.</b>	S12X-006	<b>Previous Inspection:</b>	February 12, 2013
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	August 06, 2013
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Drill Sites		
<b>Current Stage of Operation:</b>	Completed		
<b>Program Modifications Approved:</b>	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Drill Sites				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**

Water Wells:

As stated in an earlier Inspection Report, mulchers will be onsite to dispose of brush. This has been carried out. No erosion concerns, sites have been cleared and re-gen. evident. The drill waste has been incorporated into the road and seems to have worked well.

Please ensure all water wells have the appropriate signage as per Condition Q.15.

All conditions acceptable.

Not Available

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Date:	August 06, 2013	Permit #:	S12X-006	Page No:	2
-------	-----------------	-----------	----------	----------	---