



Aboriginal Affairs and
Northern Development Canada

Affaires autochtones et
Développement du Nord Canada

<http://www.aandc-aadnc.gc.ca>

<http://www.aadnc-aandc.gc.ca>

North Mackenzie District
P.O. Box 126
Norman Wells, NT, X0E 0V0

Telephone: 867 587-2911
Fax: 867-587-2928

February 4, 2014

Husky Oil Operations Limited
Box 6525, Station D
Calgary, AB T2P 3G7

Attn: Ken Hansen

**RE: Land Use Permit S13X-003
Quarry A and Access**

Dear Ken Hansen,

An inspection of the above noted operation was conducted on January 30, 2014 by the undersigned. Enclosed is a copy of the Environmental Inspection Report.

The inspection was carried out to verify that Quarry A had not been utilized. Husky Energy has stated that this site will not be developed and has requested a return of royalties.

On one other note, the request to widen the access road from Km 9 to 12 by 3 meters is approved.

If you have any questions, please contact me at 867 587-2911.

Sincerely,

Steve Deschene
Resource Management Officer III

Cc: Inuvik District Office
Sahtu Land and Water Board
National Energy Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Husky Oil Operations Limited	Permit Expiry Date:	
Land Use Permit No.	S13X-003	Previous Inspection:	New
Quarrying Permit No.	2013QP0005	Inspection Date:	January 30, 2014
Contractor:		Subcontractor:	
Location(s) Inspected:	Quarry A and Access		
Current Stage of Operation:	Awaiting crushed rock to cap the all weather road.		
Program Modifications Approved:	Widening of access from KM 9 to KM 12 by a distance of 3 meters to allow for the safe passage of haul equipment.		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected		
	Quarry A	Access	
Location as Permitted	A	A	
Time as Permitted	A	A	
Equipment as Approved (Type & Size)	A	A	
Methods & Techniques	A	A	
Facilities	A	A	
Erosion (Control or Prevention)	A	A	
Chemicals	A	A	
Wildlife and Fisheries Habitat (Protection)	A	A	
Wastes	N/A	N/A	
Historical / Archaeological Sites	A	A	
Ecological Resources	A	A	
Fuel Storage	N/A	N/A	
Brush Disposal	A	A	
Restoration of Lands	A	A	
Permits	N/I	N/I	
Matters not Inconsistent	A	A	

Explanatory Remarks -

Quarry A:

Quarry A was inspected to ensure that no activity had taken place. Husky Energy is seeking the return of royalties as this quarry will not be used. Let it be known that aside from test pitting, no resources were removed from this area.

Access:

Access was inspected from the Security check point to Quarry A. Please be advised that the Program Modification to allow a further 3 meters of clearing from Km 9 to 12 is approved.

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1 View of Quarry A from the access road. Looking west. No sign of activity.



Figure 2. Opposite side of the access road from the previous photo.





ENVIRONMENTAL INSPECTION REPORT

Figure 3 Unfortunately the material present in this area was unsuitable.



Figure 4 Access used to test pit.

