



Telephone: 867 587-7202

Fax: 867-587-2928

December 19, 2018

Husky Oil Operations Limited
Box 6525, Station D
Calgary, AB T2P 3G7

Attention: Chris Salewich

File Number	S13X-003
Type of Operation	MISC.
Location	Security Station/Winter Access Road/Staging Area

Dear Mr. Salewich,

An inspection of the above noted operation was conducted on December 18, 2018 by Regional Superintendent Steve Deschene and Resource Management Officer II Jonathan Gillingham.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the operation conditions and general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 587-7202.

Sincerely,

Original Signed

Steve Deschene
Regional Superintendent
Department of Lands
Sahtu Region

CC: Sahtu Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Husky Oil Operations Limited	Permit Expiry Date:	October 23, 2018
Land Use Permit No.	S13X-003	Previous Inspection:	June 08, 2016
Quarrying Permit No.	N/A	Inspection Date:	December 18, 2018
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	Security Station/Winter Access Road/Base Camp Staging Area		
Current Stage of Operation:	Pre Well Abandonment and Groundwater Decommissioning		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Access	Camp			
Location as Permitted	A	A			
Time as Permitted	A	A			
Equipment as Approved (Type & Size)	A	A			
Methods & Techniques	A	A			
Facilities	A	A			
Erosion (Control or Prevention)	A	A			
Chemicals	N/A	N/A			
Wildlife and Fisheries Habitat (Protection)	A	A			
Wastes	A	A			
Historical / Archaeological Sites	A	A			
Ecological Resources	A	A			
Fuel Storage	A	A			
Brush Disposal	A	A			
Restoration of Lands	N/A	N/A			
Permits	N/A	A			
Matters not Inconsistent	A	A			
Sections 12 to 19 T.L.U.R.	N/A	N/A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A			

Explanatory Remarks:

Inspectors are very pleased to report on the outstanding job Husky has completed thus far. The entire site was immaculate, all permitted conditions are being followed. The permittee is very diligent in requiring all parked vehicles are obligated to have a spill tray placed underneath, exceeding their permitted requirement. The inspectors are very satisfied with the condition of the winter access road, security station staging area, and the base camp staging area.

There are no issues or concerns at this time.



ENVIRONMENTAL INSPECTION REPORT

--

Not Available

Original Signed

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1
Security quarters



Figure 2
Required signage as per Water Licence



Figure 3
Crew monitoring ice crossing conditions/ice crossing profiling (Mackenzie River)



Figure 4
Contents of onsite spill kit



Figure 5
Water Truck extracting water



Figure 6
Security station





ENVIRONMENTAL INSPECTION REPORT

Figure 7
Sewage treatment facility and pickup with appropriate spill tray containment



Figure 8
Sewage treatment machinery



Figure 9
Generator Shed



Figure 10
Building containing portable water tank



Figure 11
Operations pick ups with proper spill containment trays



Figure 12
Current construction camp site





ENVIRONMENTAL INSPECTION REPORT

Figure 13

Water truck leaving fill up station (Mackenzie River)



Figure 14

Onsite spill response kit

