



Telephone: 867-587-7205

Fax: 867-587-2928

March 18, 2019

Enbridge Pipelines Inc.
10175 101 St. NW
Edmonton, AB T5J 0H3

Attention: Peter Cushman

File Number	S17P-005
Type of Operation	PIPELINES (existing)
Location	Camp

Dear Peter Cushman,

An inspection of the above noted operation was conducted on March 14, 2019 by Resource Management Officer II Jonathan Gillingham and Manager of Resource Management Trevor Bremner.

Enclosed is a copy of the Environmental Inspection Report. Inspectors were pleased with the camp site, no concerns at this time.

If you have any questions, please contact me at 867-587-7205.

Sincerely,

Jonathan Gillingham
Resource Management Officer II
Department of Lands
Sahtu

CC:

Sahtu Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Enbridge Pipelines Inc.	Permit Expiry Date:	February 06, 2020
Land Use Permit No.	S17P-005	Previous Inspection:	February 23, 2018
Quarrying Permit No.	NA	Inspection Date:	March 14, 2019
Contractor:	NA	Subcontractor:	NA
Location(s) Inspected:	Camp		
Current Stage of Operation:	Demobilization		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Camp				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	N/A				
Methods & Techniques	N/A				
Facilities	A				
Erosion (Control or Prevention)	N/A				
Chemicals	N/A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	N/A				
Ecological Resources	N/A				
Fuel Storage	N/A				
Brush Disposal	A				
Restoration of Lands	N/A				
Permits	N/A				
Matters not Inconsistent	N/A				
Sections 12 to 19 T.L.U.R.	N/A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Camp:

Inspectors were pleased to see the entire camp demobilized. Camp area was left very tidy, no signs of debris, only objects left on site were a porta-potty and a portable staircase. Inspectors were informed those items are to be trucked out.

Due to the stage of the project, we were unable to inspect the dig sites. Enbridge had dig site access' blocked with snow berms to restrict unauthorized access. A final seasonal inspection will take place soon. During this inspection, inspectors will inspect the camp area again and the dig sites.

Date:	March 14, 2019	Permit #:	S17P-005	Page No:	1
-------	----------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspectors would like to encourage Enbridge to keep up the excellent work, thank you for your cooperation.

NA

Representative Signature

Inspector's Signature