



February 19th, 2019

NWT Power Corporation
Box 2250
YELLOWKNIFE, NT X1A 2P7

Attention: Mr. Robert Sunderland

**Re: Land Use Permit W2014F0002
Winter Road
Snare Forks to Whati/Gamètì Winter Road Junction, NT**

Dear Mr. Sunderland,

An inspection of the winter road from the Whati/Gamètì junction to the Snare Forks Hydro Facility was conducted by Inspectors Clint Ambrose and Brandon Bradbury on February 19th, 2019. The inspection was carried out to ensure operating conditions annexed the above noted land use permit are being adhered to during this land use operation.

Approximately nine (9) kilometres of the winter road was driven and unfortunately 10 cm of ice and/or snow pack was not present to meet the requirements of Condition #8 of the land use permit. This concern was discussed with Mr. Robert Sunderland (Permittee) upon completion of the inspection and the Inspector was informed that the Contractor will be bringing a water truck to the land use area.

This cooperation is appreciated and once the water truck is actively working, the Inspectors must be notified so another inspection can be scheduled. Your copy of the Environmental Inspection Report is enclosed and should be self-explanatory.

If you have any questions or concerns, please contact the undersigned at (867) 767-9188 or Mr Brandon at (867) 767-9187 ext. 24193.

Sincerely,

Clint Ambrose
Manager, Resource Management (Inspector)
North Slave Regional Office
GNWT – Department of Lands

cc: WLWB
Weatherby Trucking Ltd. – via email



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Power Corporation	Inspection Date – February 19 th , 2019
------------	-----------------------	--

		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	W2014F0002	October 26 th , 2019	February 27 th , 2018
Quarry Permit No.			
Contractor:	Weatherby Trucking Ltd.	Sub-Contractor:	

Location(s) Inspected:	The winter road from the Whati/Gamèti junction to the Snare Forks Hydro Facility.
------------------------	---

Current Stage of Operation:	Winter road has been dragged and additional work is still required to meet Condition #8 of the land use permit.
-----------------------------	---

Program Modifications Approved:	
---------------------------------	--

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable

	Operating Condition	Aspect Inspected			Condition
		Winter Road			
A	Location and Area	A			
B	Time	A			
C	Type and Size of Equipment	A			
D	Methods and Techniques	A*			#8 Winter Roads
E	Type, Location, Capacity and Operation of All Facilities	A			
F	Control or Prevention of Ponding of Water, Flooding, Erosion, Slides and Subsidence of Land	A			
G	Use, Storage, Handling and Ultimate Disposal of Any Chemical or Toxic Material	A			
H	Wildlife and Fisheries Habitat	A			
I	Storage, Handling and Disposal of Refuse or Sewage	A			
J	Protection of Historical, Archeological and Burial Sites	A			
K	Objects and Places of Recreational, Scenic or Ecological Value	N/A			
L	Security Deposit	N/A			
M	Fuel Storage	A			
N	Methods and Techniques for Debris and Brush Disposal	A			
O	Restoration of the Lands	A			
P	Display of Permits and Permit Numbers	A			
Q	Matters Not Inconsistent With the Regulations	N/A			
R	Sections 8 to 16 M.V.L.U.R.	A			



ENVIRONMENTAL INSPECTION REPORT Pg. 2

Date: February 19th, 2019

Permit #: W2014F0002

Explanatory Remarks

An inspection of the winter road from the Whati/Gamèti junction to the Snare Forks Hydro Facility was conducted by Inspectors Clint Ambrose and Brandon Bradbury on February 19th, 2019. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit are being adhered to during this land use operation.

The Inspectors were provided notification on January 11th, 2019 that winter road construction was to commence on January 16th, 2019 westerly from the Hydro Facility towards the junction. There was no activity at the time of the inspection and approximately nine (9) kilometres of the winter road was inspected.

Unfortunately sufficient icing and/or snow pack (10 cm) wasn't present along the entire route (Photo #1 & #2) which is a requirement of Condition #8 of the land use permit. This concern was discussed with Mr. Robert Sunderland (Permittee) upon completion of the inspection and the Inspector was informed that the Contractor is currently making arrangements to bring a water truck into the land use area to finish construction of the winter road prior to use by the Permittee.

This cooperation to comply with all operating conditions of the permit is appreciated and once the water truck is actively working, the Inspector must be notified so that another inspection can be scheduled.

No other concerns were noted during the inspection.

Completed off Site
Representative's Signature

Clint Ambrose
Inspector


Inspector's Signature



Photo #1 - W2014F0002 - NTPC - Share Hydro Winter Road
Looking north at the winter road alignment.



Photo #2 - W2014F0002 - NTPC - Share Hydro Winter Road
Although snow was present, requirements of Condition #8 of the land use permit have not been met.