



**Indian and Northern
Affairs Canada**
www.inac.gc.ca

North Mackenzie District
P.O. Box 2100
Inuvik, NT X0E 0T0

**Affaires Indiennes
et du Nord Canada**
www.ainc.gc.ca

Telephone: 867 777-8900
Fax: 867-777-2090

RECEIVED
SEP 09 2010

September 2, 2010

Devlan Exploration (Iteration)
700-700 2nd Street SW
Calgary, AB, T2P 2W1

Attn: Darren Tomecek

RE: Land Use Permit (G2002A0014)

Dear Mr. Darren Tomecek,

On August 31, 2010, Resource Management Officer, Donald Arey conducted an inspection of your operation under the above mentioned Land Use Permit.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report.

If you have any questions, please contact me at 867 777-8900

Sincerely,


Conrad Baetz
Manager North Mackenzie District

Cc: RMO – Inuvik
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Devlan Exploration (Iteration)
------------	--------------------------------

Permit Expiry Date: December 31, 2005 Previous Inspection: New

Land Use Permit No.	G2002A0014		
Quarrying Permit No.			
Contractor:		Subcontractor:	

Location(s) Inspected:	Tree River B-10
------------------------	-----------------

Current Stage of Operation:	complete
-----------------------------	----------

Program Modifications Approved:	
---------------------------------	--

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Tree River B-10				
Location as Permitted	A				
Time as Permitted	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -

--

N/A
Representative Signature

Inspector's Signature




ENVIRONMENTAL INSPECTION REPORT Pg. 2
(Continued)

Date:	August 31, 2010	Permit #:	G2002A0014
-------	-----------------	-----------	------------

General Comments: (Continued)

Tree River B-10:

All aspects were satisfactory at time of inspection


Inspectors Signature



ENVIRONMENTAL INSPECTION REPORT Pg. 3 (Continued)

Date:	August 31, 2010	Permit #:	G2002A0014
-------	-----------------	-----------	------------

Inspection Images:

Figure 1
Aerial



Figure 2
Aerial



Figure 3
Aerial



Figure 4
Aerial

