



Telephone: 867-777-8907

Fax: 867-777-2090

October 7, 2016

RECEIVED
OCT 19 2016

Gwich'in Development Corporation
P.O. Box 1509
Inuvik, NT X0E 0T0

Attention: Brian Penney

File Number G15Q002
Type of Operation QUARRY SITE - Existing
Location Km 44 Midway Lake

Dear Brian Penney,

An inspection of the above noted operation was conducted on October 06, 2016 by Resource Management Officer II Herbert Allen and Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Conrad Baetz, Regional Superintendent, Beaufort Delta Region

GLWB

GTC



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Gwich'in Development Corporation	Permit Expiry Date:	June 24, 2020
Land Use Permit No.	G15Q002	Previous Inspection:	September 28, 2016
Quarrying Permit No.		Inspection Date:	October 06, 2016
Contractor:	LJ Construction	Subcontractor:	
Location(s) Inspected:	Km 44 Midway Lake		
Current Stage of Operation:	on going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 44 Midway Lake pit				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Historical / Archaeological Sites	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				
Time as Permitted	A				

Explanatory Remarks -

Km 44 Midway Lake pit:

During the inspection on October 6, 2016 there was one concern observed by the inspectors. There is a small amount of garbage on the pit floor at the northeast corner of the pit.

Over all the pit looks in good order and the work on the south end of the pit is complete and is now moved to the northeast end.

NA

Representative Signature

[Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Garbage on the pit floor



Figure 2

Loading trucks with gravel



Date:	October 06, 2016	Permit #:	G15Q002	Page No:	2
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3
Stock pile



Figure 4
View of the south end

